Tune (000)	NITED STATES ENT OF THE INTERIOR	FORM APPROVED Budget Bureau No. 1004-0135
V Correction BUREAU OI	F LAND MANAGEMENT	Expires: March 31, 1993 5. Lease Designation and Serial No.
5 M 4		NMLCO46164-B
tist , sound i notice	S AND REPORTS ON WELLS	6 16 1 11 11
Do not use this form for proposals to	drill or to deepen or reentry to a different reservoir	
Use "APPLICATION F	OR PERMIT—" for such proposals	
SUBM	IT IN TRIPLICATE	7. If Unit or CA, Agreement Designation
I. Type of Well '		
Vell Well Other		8. Well Name and No.
2. Name of Operator	••••	Amerada Federal #:
Stevens & Tull, Inc.		9. API Well No.
•	V 70700 (015) (00 1/10	30-025-27132
P.O. Box 11005, Midland, T. Location of Well (Footage, Sec., T., R., M., or Survey	X 79702 (915) 699-1410	10. Field and Pool, or Exploratory Area
		Wildcat 11. County or Parish, State
Sec 17, T20S, R36E		County of Farish, State
		Lea, NM .
CHECK APPROPRIATE BOX	(s) TO INDICATE NATURE OF NOTICE, REPOR	
TYPE OF SUBMISSION		NI, UN UINER DAIA
	TYPE OF ACTION	
Notice of Intent	/ Johndonment	Change of Plans
Subsequent Report		New Construction
Subsequent Report	Elugging Back	Non-Routine Fracturing
Final Abandonment Notice	Casing Repair	Water Shut-Off
Final Adandonment Notice	Altering Casing	Conversion to Injection
	E Cther	Dispose Water
Describe Property of Completed Operations (Of 1		(Note: Report results of multiple completion on We Completion or Recompletion Report and Log form
give subsurface locations and measured and true vertic	Il pertinent details, and give pertinent dates, including estimated date of starting a depths for all markers and zones pertinent to this work.)*	any proposed work. If well is directionally dril
2/22/96 - Begin Reentry - I	Drill plug #1 From surface to 47' - 8	5/8" bit
2/23/96 - Drill plug #2 Fro	om 1316' - 1425'	
2/26/96 - Drill plug #3 Fro	om 2920' - 3030' - Drill plug #4 to 384	46' where
we found top of 7	7" csg stub	
•		
2/27/96 - Drill plug #4 to	3958' - Inside 7" csg w/6 5/8" bit tag	g CIBP @
2/27/96 - Drill plug #4 to 5300' which was r	3958' - Inside 7" csg w/6 5/8" bit tag not reported on P&A Sundry Notice - fe	g CIBP @ 11 thru @
2/27/96 - Drill plug #4 to 5300' which was r 5316'	not reported on P&A Sundry Notice - fe	11 thru @
2/27/96 - Drill plug #4 to 5300' which was r 5316' 2/28/96 - Drill plug #5 fro	not reported on P&A Sundry Notice - fe om 5334' - 5592' - wash hole down to p	ll thru @
2/27/96 - Drill plug #4 to 5300' which was r 5316' 2/28/96 - Drill plug #5 frc 2/29/96 - Run cased hole lo	not reported on P&A Sundry Notice - fe om 5334' - 5592' - wash hole down to p ogs from 6300' to 5600' to evaluate wel	ll thru @
2/27/96 - Drill plug #4 to 5300' which was r 5316' 2/28/96 - Drill plug #5 fro	not reported on P&A Sundry Notice - fe om 5334' - 5592' - wash hole down to p ogs from 6300' to 5600' to evaluate wel	ll thru @
2/27/96 - Drill plug #4 to 5300' which was r 5316' 2/28/96 - Drill plug #5 frc 2/29/96 - Run cased hole lo	not reported on P&A Sundry Notice - fe om 5334' - 5592' - wash hole down to p ogs from 6300' to 5600' to evaluate wel	ll thru @
2/27/96 - Drill plug #4 to 5300' which was r 5316' 2/28/96 - Drill plug #5 frc 2/29/96 - Run cased hole lo	not reported on P&A Sundry Notice - fe om 5334' - 5592' - wash hole down to p ogs from 6300' to 5600' to evaluate wel	ll thru @
2/27/96 - Drill plug #4 to 5300' which was r 5316' 2/28/96 - Drill plug #5 frc 2/29/96 - Run cased hole lo	not reported on P&A Sundry Notice - fe om 5334' - 5592' - wash hole down to p ogs from 6300' to 5600' to evaluate wel	ll thru @
2/27/96 - Drill plug #4 to 5300' which was r 5316' 2/28/96 - Drill plug #5 frc 2/29/96 - Run cased hole lo	not reported on P&A Sundry Notice - fe om 5334' - 5592' - wash hole down to p ogs from 6300' to 5600' to evaluate wel	ll thru @
2/27/96 - Drill plug #4 to 5300' which was r 5316' 2/28/96 - Drill plug #5 frc 2/29/96 - Run cased hole lo	not reported on P&A Sundry Notice - fe om 5334' - 5592' - wash hole down to p ogs from 6300' to 5600' to evaluate wel	ll thru @
2/27/96 - Drill plug #4 to 5300' which was r 5316' 2/28/96 - Drill plug #5 frc 2/29/96 - Run cased hole lo	not reported on P&A Sundry Notice - fe om 5334' - 5592' - wash hole down to p ogs from 6300' to 5600' to evaluate wel	ll thru @
2/27/96 - Drill plug #4 to 5300' which was r 5316' 2/28/96 - Drill plug #5 fro 2/29/96 - Run cased hole lo potential Delawar	not reported on P&A Sundry Notice - fe om 5334' - 5592' - wash hole down to p ogs from 6300' to 5600' to evaluate wel	ll thru @
2/27/96 - Drill plug #4 to 5300' which was r 5316' 2/28/96 - Drill plug #5 frc 2/29/96 - Run cased hole lo	not reported on P&A Sundry Notice - fe om 5334' - 5592' - wash hole down to p ogs from 6300' to 5600' to evaluate wel	ll thru @
2/27/96 - Drill plug #4 to 5300' which was r 5316' 2/28/96 - Drill plug #5 fro 2/29/96 - Run cased hole lo potential Delawar	not reported on P&A Sundry Notice - fe om 5334' - 5592' - wash hole down to p ogs from 6300' to 5600' to evaluate wel	11 thru @ lug #6 @ 7458' 11 bore. For Abres 3/12/96
2/27/96 - Drill plug #4 to 5300' which was r 5316' 2/28/96 - Drill plug #5 fro 2/29/96 - Run cased hole lo potential Delawar	not reported on P&A Sundry Notice fe om 5334' - 5592' - wash hole down to p ogs from 6300' to 5600' to evaluate we re completion.	11 thru @ lug #6 @ 7458' 11 bore. For
2/27/96 - Drill plug #4 to 5300' which was r 5316' 2/28/96 - Drill plug #5 fro 2/29/96 - Run cased hole lo potential Delawar potential Delawar	not reported on P&A Sundry Notice fe om 5334' - 5592' - wash hole down to p ogs from 6300' to 5600' to evaluate we re completion.	11 thru @ lug #6 @ 7458' 11 bore. For Abres 3/12/96
2/27/96 - Drill plug #4 to 5300' which was r 5316' 2/28/96 - Drill plug #5 fro 2/29/96 - Run cased hole lo potential Delawar	not reported on P&A Sundry Notice fe om 5334' - 5592' - wash hole down to p ogs from 6300' to 5600' to evaluate we re completion.	11 thru @ lug #6 @ 7458' 11 bore. For Abres 3/12/96
2/27/96 - Drill plug #4 to 5300' which was r 5316' 2/28/96 - Drill plug #5 fro 2/29/96 - Run cased hole lo potential Delawar potential Delawar	not reported on P&A Sundry Notice fe om 5334' - 5592' - wash hole down to p ogs from 6300' to 5600' to evaluate we re completion.	11 thru @ lug #6 @ 7458' 11 bore. For Amo 3/12/96

See Instruction on Reverse Side

.

APR 1996 APR 1996 Hoope Hoope A CONTRACTOR

34567