

Form 3160-5  
(June 1990)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☐ Gas Well ☐ Other ☒ X-Water supply well

2. Name of Operator

Aandarko Petroleum Corporation

3. Address and Telephone No.

P.O. Drawer 130, Artesia, N.M. 88211-0130

4. Location of Well (Frontage, Sec., T., R., M., or Survey Description)

1330 FNL & 1330 FWL, Sec. 14, T-20S, R-33E

FORM APPROVED

Budget Bureau No. 1001 0135

Expires: March 31, 1993

5. Lease Designation and Serial No.

LC 065658

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

Teas Yates Unit

8. Well Name and No.

Teas Yates W Fed #1

9. API Well No.

30 025-133

10. Field and Pool, or Exploratory Area

Teas Capitan Reef

11. County or Parish, State

Lea county, N.M.

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☒ Other Clean out to PBTD  
☐ Change of Plans  
☐ New Construction  
☐ Non Routine Fracturing  
☐ Water Shut Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Note: This water supply well quit giving up water. RUPU and pulled pump. WIH and found fill at 2735'. TOH. WIH with bit and cleaned out scale and fill to 2785' when hit possible junk or bad casing and could not make any more hole. TOH. RDPU and waited for orders. Now plan to try to wash over possible junk and clean out to PBTD.

1. RUPU.
2. GIH with 6 1/4" bit and clean out 7 5/8" casing down to 5 1/2" liner top at 2688'. TOH.
3. GIH with 4 3/4" shoe and clean out to obstruction in 5 1/2" at 2735'. Wash or cut over obstruction and TOH.
4. GIH with bit and clean out to the PBTD of 3826'.
5. Return well to pump. RDPU.

14. I hereby certify that the foregoing is true and correct

Signed Mike Brumwell

Title Field Foreman

Date 11-10-92

(This space for Federal or State office use)

Approved by \_\_\_\_\_  
Conditions of approval, if any:

Title \_\_\_\_\_

Date 11/30/92

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*See instructions on Reverse Side

RECEIVED  
DEC 03 1992  
CWD HOBBS OFFICE