STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

40. 07 COPIES SECCIVES		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.O.S.	T_{-}	
LAND OFFICE		
OPERATOR		

OIL CONSERVATION DIVISION

DISTRIB	UTION	P. O. BOX 2088			Form C-103 Revised 10-1-7			
SANTA FE		SANTA FE, NEW MEXICO 87501				KE41260 10-1	٠,	
FILE			•			Sa. Indicate T	ype of Lease	
U.S.D.S.						State	Foo X	1
LAND OFFIC	E						Gas Lease No.	
OPERATOR						5, Sidie Off &	Gds Ledse No.	
	CLINI	DDV MOTICES	AND DEDORTS ON	WELLS		mmm	ATTITITI TO	1
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PAOPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT —" (1911) FOR SUCH PROPOSALB."					7			
01L	WELL X	OTHEM-				7. Unit Agreer		
, Name of Operator						B. Farm or Le	ase Name	
lke	Lovelady,	Inc.				Linwo	od	
d. Address of Cperc						9. Well No.		
P.0	. Drawe r 26	666; Midland,	, Texas 797	02		1		
4. Location of Well						10. Field and	Pool, or Wildcat	
	F.	19801	FROM THE WEST	LINE AND	380 FEET F	Now Wildo	at	
UMII CE. 12.								//
nor	th	30	TOWNSHIP19	I-S BANGE	38-E NN	PM (11111)]]
191								2
THITTE	TITITITI	15. E	Elevation (Show whether	DF, RT, GR, etc	.)	12. County		/
			3603.4	GR.		Lea		//
16.	77777777	d Appendice	Box To Indicate N		ice Report or			_
				vature or Non	-	ENT REPORT O	\ C •	
	NOTICE OF	FINTENTION T	0:		20025005	IN REPORT O	· F •	
			PLUG AND ABANDON	REMEDIAL WORK		A 1:	TERING CASING	Γ
PERFORM REMEDIAL	Ħ .		PEGG AND ABANDON []	COMMENCE DRIL	三		JG AND ABANDONMENT	۲
TEMPORARILY ABAH	7-3			1	7	7.0	AND ABAROUMERI	L_
PULL OR ALTER CAS	ING		CHANGE PLANS	CASING TEST AN		on Report		ſγ
				OTHER	Completi	on kepont		ιΔ
OTHER								
17. Describe Propo	osed or Completed	d Operations (Clearl	ly state all pertinent det	ails, and give per	tinent dates, includ	ding estimated date	of starting any propo	s c
work) SEE RU		s Dia up wo	11 sorvice unit	-				
7/17/81	move III	c kig up we	ll service unit	. •				
7/18/81	Ran GRN	Collar Lon	from 4013' back	to 27001	Perf W/411	Csa aun 2	shots/Ft	
// 10/01			4, 2963, 65, 67				3110 (37) (
	2001, 0	5, 05, 52, 5	4, 2303, 03, 07	, 03, 5103	, 11, 12, 12	, 1/.		
7/19/81	Treat Pe	Treat Perfs. W/2000 Gal 15% NEA. & Swab test.						
_		4.						
7/23/81			3117' W/30,000				W/60,000	
	20/40# 9	sand & 7,000;	# 10/20# sand.	Flow & Swa	ab to test t	ank.		
7/30/8 1	Shut in	waiting on	4-point test.					

18. I hereby certify that t	he information above is true and c	omplete to the best of my knowledge and belief.			
SIGNED Pary	11 Simo	Mgr. of Drlg. & Prod.	DATE	7/30/	81
APPROVED BY	Orfg. Signed by Jerry Sexton Dies L. Supp.	TITLE	DATE	AUG	3 1981