

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

N. M. OIL & GAS COMMISSION
P.O. BOX 1580
HOBBS, NEW MEXICO 88240

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

NM 14504

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Ike Lovelady, Inc.

3. ADDRESS OF OPERATOR

P.O. Drawer 2666, Midland, Texas 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FSL & 660' FWL Sec. 31

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3595.9 Gr.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Shearn Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 31, T-19-S, R-38-E

12. COUNTY OR PARISH 13. STATE

Lea

New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐

PULL OR ALTER CASING

☐

FRACTURE TREAT

☐

MULTIPLE COMPLETE

☐

SHOOT OR ACIDIZE

☐

ABANDON*

☒

REPAIR WELL

☐

CHANGE PLANS

☐

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐

REPAIRING WELL

☐

FRACTURE TREATMENT

☐

ALTERING CASING

☐

SHOOTING OR ACIDIZING

☐

ABANDONMENT*

☒

(Other)


(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

2-9-82 to 3-5-82 ---- Drilled 7 7/8" hole to 7150'

3-6-82 ----- Ran GRN Collar Log from 7146' back to 1700'

3-7-82 ----- Set Plugs as follows 65 Skis at 7150', 65 Skis at 6030' 65 Skis at 2959, 65 Skis at 1527', 10 Skis at Surface. Release Rig & Rig down. Install Dry Hole marker Fence Pits will Finish clean up when Pits Dry.



OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Paul Sims Paul Sims

TITLE Mgr. Of Drlg. & Prod.

DATE 3-8-82

(This space for Federal or State office use)

APPROVED BY Paul Sims

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

PA Sims Post

RECEIVED
AUG 25 1986
A.C.S.
MOBES OFFICE