

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

MAY 6 10 20 AM '91

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Grace Petroleum Corporation

Attention: Bill Baswell

3. Address and Telephone No.

6501 N. Broadway, Oklahoma City, OK 73116 (405) 840-6600

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

990' FNL & 990' FWL Sec. 12, T20S-R33E

5. Lease Designation and Serial No.

NM 40406

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Ed Smith Ranch Fed'l Com

9. API Well No.

#1-10

10. Field and Pool, or Exploratory Area

Teas Penn

11. County or Parish, State

Lea County, New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☒ Other Temporarily Abandon

- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Intent T&A Sundry Notice

NOTIFY BLM FOR A REPRESENTATIVE TO WITNESS THE CASING TEST.

1. MIRU service rig & BOPE. Kill well.
2. Pull out of permanent pkr. POOH laying down tbg. 35'
3. MIRU wireline truck. RIH & set CIBP @  $\pm 13,000'$ . Dump bail 20' cmt on top of CIBP.
4. MIRU pump truck w/pressure recorder. Pressure up on csg to 500 psi surface pressure and record test for 30 min.
5. RD pump truck & shut well in.

14. I hereby certify that the foregoing is true and correct

Signed

William P. Baswell

Title Operations Engineer

Date 5/1/91

(This space for Federal or State office use)

Approved by

One Signature

Title

SEAL OF THE BUREAU

Date

5.20.91

Conditions of approval, if any: