N. M. DIE CONS. COMMISSION

P. O. BOY 1980

1980 Form Approved.
Budget Bureau No. 42–R1424

***	DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE NM 29704 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY (Do not use this for reservoir, Use Form	NOTICES AND REPORTS ON WELLS m for proposals to drill or to deepen or plug back to a different 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME
1 oil —	gas	6. FARM OR LEASE NAME
well LX	well other	South Teas Federal 9. WELL NO.
2. NAME OF O		11
Julian A 3. ADDRESS OF	rd F OPERATOR	10. FIELD OR WILDCAT NAME
	17360, Ft. Worth, TX 76102	Wolfeamp - Wildeat Sicce
4. LOCATION O	F WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY O
below.)	::1980' FNL & 2310' FEL	Sec. 23, T20S, R33E
AT TOP PRO	D INTERVAL: 44 FOOT	12. COUNTY OR PARISH 13. STATE
AT TOTAL DI	EPTH: 14,316'	New Mexico
16. CHECK APPE	ROPRIATE BOX TO INDICATE NATURE OF NOTICE	14. API NO.
REPORT, OR REQUEST FOR A	OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD 3617' GR
PULL OR ALTER MULTIPLE COMP CHANGE ZONES ABANDON*	CASING	(NOTE: Report results of multiple completion or zon change on Form 9–330.)
other)	ROPOSED OR COMPLETED OPERATIONS (C)	
other) 17. DESCRIBE Princluding esti	ROPOSED OR COMPLETED OPERATIONS (Clearly state mated date of starting any proposed work. If well is did true vertical depths for all markers and zones pertinent	e all pertinent details, and give pertinent dates rectionally drilled, give subsurface locations and t to this work.)*
other) 17. DESCRIBE Princluding estimeasured and 02-21-84	true vertical depths for all markers and zones pertinent Hot oil well & clean up	t to this work.)*
other) 17. DESCRIBE Princluding estimeasured and 02-21-84	Hot oil well & clean up Rig up Clarke Oil Well Service pull	t to this work.)*
other) 17. DESCRIBE Princluding estimeasured and 02-21-84	Hot oil well & clean up Rig up Clarke Oil Well Service pull BOP. Release tbg. anchor. Pull th	t to this work.)*
17. DESCRIBE Princluding estimeasured and 02-21-84	Hot oil well & clean up Rig up Clarke Oil Well Service pull BOP. Release tbg. anchor. Pull th 388 jts. 2 3/8" EUE 4.70# N80.	tion this work.)* Ling unit. Nipple up hydraulic og. Strap tbg. out of hole rip in hole with tubing. Tagged
Other) 17. DESCRIBE Princluding estimeasured and 02-21-84 02-22-84 02-23-84 O2-23-84 Subsurface Safety 8. I hereby certify agree Acceptance	Hot oil well & clean up Rig up Clarke Oil Well Service pull BOP. Release tbg. anchor. Pull th 388 jts. 2 3/8" EUE 4.70# N80. Pick up bit and 4 drill collars. Tr up on bridge plug @ 13,509'. Drill with 10# brine water to top of brid Circulate hole clean Valve: Manu. and Type THILE THILE (This space for Federal or State office)	to this work.)* Ling unit. Nipple up hydraulic og. Strap tbg. out of hole pip in hole with tubing. Tagged out cement fill, displace hole lige plug. Drill out bridge plug. Set @Ft

Carlelad, NEW MEXICO . See Instructions on Reverse Side