

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Maralo, Inc. 3. Address of Operator P. O. Box 832, Midland, Texas 79702 0832 4. Location of Well UNIT LETTER <u>I</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>467</u> FEET FROM THE <u>East</u> LINE, SECTION <u>12</u> TOWNSHIP <u>19S</u> RANGE <u>38E</u> NMPM.	7. Unit Agreement Name 8. Farm or Lease Name Cain 9. Well No. 1 10. Field and Pool, or Wildcat Wildcat (San Andres)
15. Elevation (Show whether DF, RT, GR, etc.) 3609.1 GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 7-18-83 Set wireline bridge plug @ 4350'. Ran 138 jts 2 3/8" tbg to top of CIBP @ 4350'. Circ'd csg. w/9.5# mud laden fluid. Spotted 5 sx. cmt. on top of CIBP. POOH
- 7-19-83 Found free-point of 5 1/2" csg. @ 2444'. Ran jet cutter on wireline. Cut 5 1/2" csg. @2405'. LD 77 jts. 5 1/2" K-55 14# csg. Ran 78 jts. 2 /38" tbg. to 2455'. Loaded hole w/9.5 mud laden fluid. Spotted 40 sx Cl. "C" cmt. plug from 2455 up.
- 7-20-83 Ran 74 jts. 2 3/8" tbg. Tagged top of cmt. plug @ 2345'. Pld up to 1820'. Spotted 50 sx Cl. "C" cmt. from 1829 - 1648'. Waited 4 1/2 hrs & tagged plug @ 1648'. POOH LD 2 3/8" tbg. Put 25' cmt. plug @ surface. Removed BOP. Cut off csg. & installed dry hole marker. Well P & A'd 7-20-83

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Brenda Coffman TITLE Agent DATE 7-26-83

APPROVED BY R. A. Valli TITLE OIL & GAS INSPECTOR DATE MAR 22 1988

CONDITIONS OF APPROVAL, IF ANY: