

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator AMOCO PRODUCTION COMPANY	8. Form or Lease Name Best
3. Address of Operator P.O. BOX 68, HOBBS, NEW MEXICO 88240	9. Well No. 2
4. Location of Well UNIT LETTER <u>P</u> <u>840</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>23</u> TOWNSHIP <u>20-S</u> RANGE <u>35-E</u> N.M.P.M.	10. Field and Pool, or Wildcat East Featherstone Bone Springs
11. Elevation (Show whether DF, RT, GR, etc.) 3670.9' GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to Plug and Abandon the subject well as follows:
MISU and POH with production equipment. RIH and retrieve RBP set at 9770'. RIH with CIBP and set at 9650'. Cap CIBP with 35' cement. Run free point and shoot. Pull 5 1/2" casing. Temperature survey shows TCMT at 7425'. Displace hole with plugging mud. Spot 25 SX class H heat cement from 50' inside casing stub to 50' outside casing stub. Spot 30SX class C heat from 4566'-4466' (50' cement inside and outside 8 7/8" casing shoe @ 4516') Spot 30SX class C heat from 665'-565' (50' cement inside and outside 13 3/8" casing shoe @ 615') Spot 10' cement plug at surface and erect abandonment marker. Clean location.

OTS NMOC, Hobbs 1-JRB 1-FJN 1-GMH 1-Superior, Mid.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles M. Lerring TITLE ADMINISTRATIVE ANALYST (SG) DATE 8/22/85
ORIGINAL SIGNED BY ADMINISTRATIVE ANALYST
APPROVED BY _____ TITLE _____ DATE AUG 22 1985
CONDITIONS OF APPROVAL, IF ANY: