

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.

30-025-28352

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

A-1212-1

7. Lease Name or Unit Agreement Name

South Hobbs (GSA) Unit

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well

OIL
WELL ☒

GAS
WELL ☐

OTHER ☐

2. Name of Operator

Amoco Production Company

(Rm 17.182)

8. Well No.

149

3. Address of operator

P.O. Box 3092,

Houston,

Texas

77253-3092

9. Pool name or Wildcat

Hobbs Grayburg - San Andres

4. Well Location SL/BHL

Unit Letter A

150/23 Feet From The

North

Line and

380/9

Feet From The

East

Line

Section

9

Township

19-S

Range

38-E

NMPM

Lea, NM

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3608' GL

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Acidize ☒

OTHER: ☐

SUBSEQUENT REPORT OF:

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103.

1. POH WITH PRODUCTION TEST EQUIP. INSPECT & REPAIR EQUIPMENT AS NECESSARY.

PUMP AT 5 BPM & LIMIT PRESSURE TO 2000 PSI ABOVE RFC OPENING.

2. PERF X 4 SPF X 90 OR 100 DEGREE PHASING THE FOLLOWING: 4186-95, 4201-4207, 4219-4256, 4236-4275.

4. FLUSH TO PERFS WITH 40 BBLs CLEAN WATER.

5. RELEASE PKR AND POH.

3. RIH WITH WORKSTRING AND PACKER & SET PACKER X 4175'. ACIDIZE PAY W/ 5000 GAL 20% NE HCL CONTAINING 2 GAL/1000 GAL WA-211 & 2 GAL/1000 GAL WA-212.

6. RIH WITH PRODUCTION EQUIPMENT AS PULLED ABOVE & RETURN WELL TO PRODUCTION.

7. PUMP SCALE SQUEEZE TO INHIBIT SCALE FORMATION.

PUMP IN 3 STAGES AS FOLLOWS: 1500 GAL ACID
400 # ROCK SALT
1500 GAL ACID
600 # ROCK SALT
2000 GAL ACID

** ROCK SALT AMOUNTS ARE GUIDELINES ONLY... PUMP TIL YOU SEE BLOCK

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Devina M. Prince

TITLE

Staff Assistant

DATE 12-02-93

TYPE OR PRINT NAME: Devina M. Prince

TELEPHONE N. (713) 366-7686

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT I SUPERVISOR

TITLE

CONDITIONS OF APPROVAL, IF ANY

DEC 09 1993