## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

**. ** ( **)** ***(****	
DISTRIBUTION	
BANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
PERATOR	

## OIL CONSERVATION DIVISION

DISTRIBUTION  BANTA FE		P. O. BOX 20			Form C-103 - Revised 19-1-73		
FILE	SA	NTA FE, NEW M	EXICO 87501				
U.S.G.S.				I —	Sa. Indicate Type of Lease		
DPERATOR	<del>  </del>		•	State X	Fee [		
3. 2	لسما			5. State Oil & Gas			
CLIA	NODY NOTICES AND			A-1212-	. 1		
OU) Too NOT USE THIS FORM FOR USE "APPL	NORY NOTICES AND PROPOSALS TO DRILL OR LICATION FOR PERMIT - " I	D REPORTS ON WE	LLS TO A DIFFERENT RESERVOIR.				
	TOTAL FOR PERMIT TO ()	FORM C-101) FOR SUCH PRO	OP052L5.)	7 1/2// 4 22 2 22 2	711111111111111111111111111111111111111		
MELL X WELL	OTHER-			7. Unit Agreement	Name		
Name of Operator		<del></del>		8. Farm or Lease	Name		
	OCO PRODUCTION COMPANY				South Hobbs (GSA)		
Address of Operator	- NH 00040			9. Well No.			
P. 0. Box 68, Hobb	is, NM 88240			155			
SL/BHL D	1150/1210	N = 4 ls	1299	10. Field and Poo			
SHIT LETTER	1158/1310	M THE NORTH	1568/4330 (	Hobbs GSA	1		
East	a	. 10 c					
THE LINE, SI	ECTION	TOWNSHIP 19-3		··· ()			
	15. Eleve	ation (Show whether DF.	PT CP		777777777		
		3604' GL	-	12. County Lea	IIIIIII		
. Chec	ck Appropriate Box	To Indiana Name	- ()	·			
NOTICE OF	F INTENTION TO:	. To indicate Natui	re of Notice, Report or	Other Data			
•			2083E005	NT REPORT OF:	÷		
ERFORM REMEDIAL WORK	PLUC	G AND ABANDON REN	MEDIAL WORK	\$1.00m	G CASING		
EMPORARILY ABANDON		cor	MMENCE DRILLING OPHS.		D ABAHDOHMENT		
ULL OR ALTER CASING	CHAI	NGE PLANS	SING TEST AND CEMENT JOS		N NO NO ON MENT		
			OTHER				
OTHER		Lil	•				
Describe Proposed or Completed work) SEE RULE 1103.	Operations (Clearly sta	ite all pertinent details, (	and eive pertinent dates isolid	· · · · · · · · · · · · · · · · · · ·			
work) SEE RULE 1103.			and gree personent dates, therea	ing estimated date of st	arting any proposed		
MIRUSU 6-2-87 and	d null rods num	on and tubing	Run PPIP and 2-7/8"				
acidize perfs fro	om 4168-4252 wit	th 75 gallons/fi	t of perfs 20% NE HC	tubing and			
additives. Pull	tubing and pack	ker. Run 2-7/8'	" tubing and install	numning			
equipment. Retur	n to production	and MOSU 6-2-8	87.	Pumping	7		
		· <b>X</b>					
PPW		426 BWPD x 10					
PAN	10: 32 BOPD x	378 BWPD x 5	MCFD.		· .		
			•				
			•	•			
		· · · · · · · · · · · · · · · · · · ·					
	. 4				:		
	ı						
I hereby construction that the feet				•			
I hereby certify that the informati	on above is true and com	iplete to the best of my k	nowledge and belief.				
CXXXXIII	. 0 8						
···· O! M. Witchell		Sr. Admi	n. Analyst	BATE 6-9-	-87		
Omin a	ion . 11						
Paul	igned by Kautz			IIIM ·	1 1 1987		
Gen	logist	- TITLE	<del></del>	DATE JUIT	<u> </u>		
IDITIONS OF APPROVAL, IF AN	141				<del></del>		