STATE OF NEW MEXICO

HOT AND MATERIALS DE	PAH	I IV.E
	Ĭ	
DISTRIBUTION	Ī	
BANTAPE		
FILE		
U.S.G.S.	1	
LAND OFFICE .		

OIL CONSERVATION DIVISION

DISTRIBUTION	Р О. ВО	C 2088	Form C-103 Fevised 10-1-7
BANTAPE	SANTA FE, NEW	MEXICO 87501	7641364 13-1 7
FILE			Sal Indicate Type of Lemo
U.S.O.S.			State X Fre
LAND OFFICE			5. Trate CA. 6 Gas Lease Los.
OPPEATOR			A-1212-1
			M-1515-1
SUNDRY	Y NOTICES AND REPORTS ON	WELLS	
	A DULA TO CALL OF AD OF AD DIATOR PLACE ALAPON OF ALAPON OF ACT	ACE TO A DIFFERENT RESERVES.	
			7, Unit Agreement hane
OIL CAS WELL	OTHER-		
Name of Operator	OTHER.		6. I am or Leave Name
	0.8137		South Hobbs (GSA) Uni
AMOCO PRODUCTION COMPA	ANY		4. Well No.
, Address of Operator			4. t.e.i i.o.
P. O. Box 68, Hobbs, 1	NM 88240		159
. Location of Well			10. Field and Pool, or Wildcat
F 23	North	LINE AND 1675 PEET FROM	Hobbs GSA
UNIT LETTER	FEET FROM THENOT CIT	LINE AND TOTO FEET FROM	THE THE PARTY OF T
	100	30 F	XIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII
THE West LINE, SECTIO	H _ 9 TOWNSHIP 19-5	RANGE	
	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County
	3596.5	' GL	Lea ()()()()
	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ 		or Data
		lature of Notice, Report or Oth	
NOTICE OF IN	TENTION TO:	SUBSEQUENT	REPORT OF:
			<u></u>
PERFORM REMEDIAL WORK	PLUE AND ABANDON	REMEDIAL WORK	, ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING 2945.	PLUG AND ABANDONMENT
77	CHANGE PLANS	CASING TEST AND CEMENT JOB	
PULL OR ALTER CASING		status update	E TY
		OTRER	\ \ \ \ \ \ _
OTHER			
	exclose (Clearly state all pertinent det	l ails, and give pertinent dates, including	estimated date of starting any propose
unit) SEE RULE 1103.	erations (crearly state art performance		,
,			
Moved in service uni	it 12-14-83 Ran 4-3/4"	bit and drilled cement f	rom 3375' and drilled
		t collar, and cement to 4	
DV 1601 at 3387 . L	Printed out Cement, frod	corrar, and coment to a	Discours tooted
		ole with clean fresh wate	
casing 1500 psi for	30 min. Held OK. POH a	and ran logs. Perforated	intervals 4185'-90',
4192'-96', 4198'-420)2', and 4216'-20' with A	4 SPF. Ran packer and tu	bing to 4230' and
spotted 3 bbl 15% LS	STNE acid. Pulled up to	4050' and set packer. A	cidized with 2000 gal
15% ISTNE acid and 1	1000 gal 15% LSTNE HCL av	cid with 4 ball sealers p	er bbl. POH and
DIU with conting nir	onlo and tubing Tubing	landed at 4258'. Ran ro	ds and numn Tested
Kin with Seating his	prie and cubing. Tubing	22 Cupportly numb too	ting
pump 500 psi. Moved	out service unit 12-20.	-83. Currently, pump tes	ting.
0 5 111000	0-1 11011 D. 01 150	E 1 Mach HOU Dm 4 0	OF 1 CMH 1 Toyaco
O+5-NMOCD,H I-R. E.	ugaen, Huu km. 21.150	-F. J. Nash, HOU Rm. 4.2	OU I-CHIL I-LEXACO
1-Shell 1-Sun 1-Pet	ro Lewis		
		of an browled a sad belief	
18. I hereby certify that the information	rbove is true and complete to the best	or my anowieage and periet.	
/1// 1 DS	\// .		
Knobbille	Alors,	Administrative Analyst	12-30-83
ICHED / INVENTO	 .		
ORIGINAL SIGNED B	Y JERRY SEXTON		10NA 1984
DRIGINAL TO A	JPERVISOR /		JAN 4 1984