

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-101
Revised 10-1-77

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
IG-3732

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator LYNX PETROLEUM CONSULTANTS, INC.	8. Farm or Lease Name STATE 15
3. Address of Operator P.O. BOX 1666 - HOBBS, NM 88240	9. Well No. #1
4. Location of Well UNIT LETTER <u>0</u> <u>330</u> FEET FROM THE <u>South</u> LINE AND <u>1650</u> FEET FROM THE <u>East</u> LINE, SECTION <u>15</u> TOWNSHIP <u>19S</u> RANGE <u>36E</u> N.M.P.M.	10. Field and Pool, or Wildcat Eumont Y-GR-Q
15. Elevation (Show whether DF, RT, GR, etc.) 3749.9 GR.	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1109.

Drilled 7-7/8" hole to TD (4360').
Ran 115 jts. 5-1/2", 17# & 15.5#, K-55, LT&C ST&C to 4360'.
Cement with 800 sx. Halliburton Lite + 15# salt +5# gilsonite
+ 1/4# flocele followed by 200 sx. 50/50 Poz + 2% CaCl₂.
Circulated 75 sx. cement to surface. Plug down 2:30 p.m.
Release Rig. WOCU 1/7/84

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Wes Shields</u>	TITLE <u>Vice President</u>	DATE <u>1/9/84</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT 1 SUPERVISOR	TITLE _____	DATE <u>JAN 11 1984</u>
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		

RECORDED
JAN 10 1984
O.C.D.
HOBBS OFFICE