

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.B.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-79

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT - FORM C-101 FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	8. Farm or Lease Name Selby
3. Address of Operator P. O. Box 68 - Hobbs, NM 88240	9. Well No. 1
4. Location of Well UNIT LETTER <u>N</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>1</u> TOWNSHIP <u>20-S</u> RANGE <u>35-E</u> NMPM.	10. Field and Pool, or Wildcat <u>Wildcat Delaware</u>
11. Elevation (Show whether DF, RT, GR, etc.) 3654.9' GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER Abandon and test a new interval ☒

SUBSEQUENT REPORT OF:

PLUG AND ABANDON ☐
REMEDIAL WORK ☐
COMMENCE DRILLING CONS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to abandon old interval and test the interval 5,770'-5,820' as follows:

Load well with 2% KCl. Pull tbq. and pkr. RIH with CIBP and set at 6,400'. Cap with 35' of Class "C" Neat cement. RIH with 3-1/8" hollow carrier casing gun and perforate the interval 5,770'-5,820' w/4JSPF. POH and RIH with pkr., unloader and 2-3/8" tbq. to surface. Set pkr. at 5,670'. Swab test and evaluate. Run base GR/temp survey. Acidize with 5,000 gals of 15% NEFE HCl acid w/add. tagged with RA material. Flush acid to perms with 1000 gals of 2% KCl water. Run after job GR/temp survey. Swab to recover load and evaluate.

0=5 NMOCD Hobbs 1 - J.R. Barnett Houston 1 - F. J. Nash Houston 1 - GCC 1 - Superior Midland 1 - Superior Houston

10. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mary C. Clark TITLE Asst. Admin. Supervisor DATE May 21, 1984

APPROVED BY DISTRICT 1 SUPERVISOR TITLE DATE MAY 21 1984

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAY 21 1984

CCC
HOBBS CTR