

#28

* To circulate cmt on
production string perf'd
1500-1501 and cmt as
follows:

Cementing Record
35 s/s c'neat, 265
s/s 'A' self stress

Amt. pulled

30 s/s