

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N. M. OIL CONS. COMMISSION
P. O. BOX 1980
HOBBS, NEW MEXICO 88240

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

BTA Oil Producers

3. Address and Telephone No.

104 S. Pecos, Midland, TX 79701 (915) 682-3753

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980' FSL & 1980' FWL
Sec 24, T20S, R34E

Unit K

5. Lease Designation and Serial No.

NM 20979

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Lynch 8212 JV-P #2

9. API Well No.

30-025-29019

10. Field and Pool, or Exploratory Area

Lea Bone Spring, South

11. County or Parish, State

Lea, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other
- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

NOTIFY BLM HOBBS - 505-393-3612

Proposed Plugging Procedure

Set CIBP @ 9500' w/35' cmt on top

Spot 35 sx plug inside 5-1/2" csg @ 5550' (50' below 9-5/8" csg shoe)

Cut & pull 5-1/2" csg - top cmt @ 4420'

Spot 50 sx plug across 5-1/2" csg stub 50' below to 50' above & tag plug

Spot 75 sx plug 750' (50' below 20" csg shoe) to 50' above csg shoe & tag plug

Spot 15 sx plug @ 30' to surface

Install dry hole marker

Spot 136' cmt plug from 68' below to 68' above 13-3/8" csg shoe

RECEIVED
SEP 7 11 02 AM '93

14. I hereby certify that the foregoing is true and correct

Signed Dorothy Houston Title Regulatory Administrator

Date 9-3-93

(This space for Federal or State office use)

Approved by (ORIG. SGD.) JOE G. LARA

Title PETROLEUM ENGINEER

Date 9/27/93

Conditions of approval, if any:

RECEIVED

SEP 28 1972

DEPT. OF COMMERCE
OFFICE