

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
B-2656

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	8. Farm or Lease Name <i>South Hobbs (GSA) Unit</i>
3. Address of Operator P.O. Box 68, Hobbs, NM 88240	9. Well No. 194
4. Location of Well UNIT LETTER O 330 FEET FROM THE <i>South</i> LINE AND 2310 FEET FROM THE <i>East</i> LINE, SECTION 5 TOWNSHIP 19S RANGE 38E NMPM.	10. Field and Pool, or Wildcat <i>Hobbs GSA</i>
15. Elevation (Show whether DF, RT, GR, etc.) 3613.9' GR	12. County <i>Lea</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> <i>perf and acidize</i>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Perf'd 4240'-4222', 4210'-4202', 4200'-4196', 4192'-4178', 4164'-4160', 4150'-4142' with 4 SPF. Set pks. at 4100' and tested OK. Acidized perfs with 50 gals. 15% NE HCL per ft. Set pks. at 4040'. Acidized with 5000 gals. 15% NE HCL. Run log and banded at 4240'. Installed production equipment. MOSU 1-5-85.

0+5-NMOCB, H 1-JRB 1-FJN 1-GCC 1-Tuxaco 1-Sun 1-Shell 1-P.L. 2-Arco

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Bonita Goble* TITLE *Administrative Analyst* DATE *1-11-85*

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

APPROVED BY _____ TITLE _____ DATE **JAN 15 1985**

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JAN 14 1985

O.C.D.
HONORARY OFFICE