

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-70

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	8. Name of Lease Name South Hobbs (GSA) Unit
3. Address of Operator P.O. Box 68, Hobbs, NM 88240	9. Well No. 184
4. Location of Well UNIT LETTER <u>F</u> <u>1766</u> FEET FROM THE <u>North</u> LINE AND <u>2488</u> FEET FROM THE <u>West</u> LINE, SECTION <u>5</u> TOWNSHIP <u>19-S</u> RANGE <u>38-E</u> NMPM.	10. Field and Pool, or Wildcat Hobbs GSA
15. Elevation (Show whether DF, RT, GR, etc.) 3618.9' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <u>Plug Back</u> <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Tripped in hole with open ended drill pipe to 3567' and set plug from 3568'-3100' with 200 sxs Class H. WOC 18 hrs and TTH and tagged cmt at 2945'. Drilled cmt and dressed off plug to 3187' and TTH. TTH with Dyna Drill and drilled out cmt stingers to 3000' and resumed drilling to target location.

0+5 NMOC/DH 1-JRB 1-FJN 1-GCC 1-Tex 1-Sun 1-Shell 1-PL 2-Arco.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Eddie W. Seay</u>	TITLE <u>Asst. Admin. Analyst</u>	DATE <u>1-22-85</u>
APPROVED BY <u>Eddie W. Seay</u>	TITLE <u>Oil &amp; Gas Inspector</u>	DATE <u>JAN 24 1985</u>
CONDITIONS OF APPROVAL, IF ANY:		