

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

H. H. GILBERT, CHIEF
P. O. BOX 100
HOBBS, NEW MEXICO

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐

2. NAME OF OPERATOR
Siete Oil & Gas Corporation

3. ADDRESS OF OPERATOR
P.O. Box 2523, Roswell, NM 88201

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
SE/4 NE/4
AT SURFACE: 1980' FNL, 660' FEL
AT TOP PROD. INTERVAL: same
AT TOTAL DEPTH: same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>		<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>		<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>		<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>		<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>		<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>		<input type="checkbox"/>
ABANDON*	<input checked="" type="checkbox"/>		<input type="checkbox"/>
(other)			

5. LEASE
88240 NM-17439

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Tonto Federal

9. WELL NO.
1

10. FIELD OR WILDCAT NAME
Teas - Bone Springs

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec: 10, T-20-S, R-33-E

12. COUNTY OR PARISH
Lea

13. STATE
New Mexico

14. API NO.
30-025-29265

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3576' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

10/11/85 - Cast iron bridge plug set @ 3500'

Plugging Operations

1. Set 100 sxs cement plug from 3500' to 3250' - tag plug
2. Set 40 sxs cement plug from 1600' tp 1500'
3. Set 40 sxs cement plug from ~~375' to~~ 475' *to 575'*
4. Set 20 sxs cement plug from 50' to surface
5. Install dry hole market @ surface

(verbal approval from Bob Pitschke) Notify Vince Valdez prior to P&A

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Barclay D. Justice TITLE Production Supervisor DATE 12/11/85

Original to be retained by State Office (This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE 12-13-85

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
DEC 16 1985
C.C.D.
HOBBS OFFICE