

Form 3160-5
(November 1983)
(Formerly 9-331)

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE *
(Other instructions on reverse side)
P. O. BOX 1000

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.
NM-06570

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
-

1. OIL GAS
WELL ☐ WELL ☒ OTHER

7. UNIT AGREEMENT NAME
-

2. NAME OF OPERATOR
Read & Stevens, Inc.

8. FARM OR LEASE NAME
Laurie "D" Federal

3. ADDRESS OF OPERATOR
P.O. Box 1518, Roswell, NM 88201

9. WELL NO.
1

4. LOCATION OF WELL (Report location clearly and in accordance with State requirements. * See also space 17 below.)

At surface
660' FNL & 990' FEL

10. FIELD AND POOL, OR WILDCAT
Lea Penn

11. SEC., T., R., M., OR BLK & SURVEY OR AREA
Sec. 15-T20S-R34E

14. PERMIT NO.
-

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3642' GL

12. COUNTY OR PARISH
Lea

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON *
CHANGE PLANS

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other) RHP Test & Acidize

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input checked="" type="checkbox"/>

REPAIRING WELL
ALTERING CASING
ABANDONMENT *

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input checked="" type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

2-15-86 SI for 72hr build-up.

2-16-86 SI RHP build-up.

2-17-86 SI RHP build-up.

2-18-86 Plld BHP bombs, opnd up to flw @ 11:00am, SITP 1483psi, flwg on 3/4" chk @ 50psi, 6hrs made 35 BO, 22 BW, left opn overnite, 72hr build-up press 3587.1psi, P* 3755psi, @ 6:00am 2-18-86 flwg @ 110psi on 22/64" chk, 7 BRLS/hr ttl fl, 50/50 O&W, rec'd ttl 99 BRLS, GG, 200 MCFD.

2-19-86 Flwg @ 100psi, 5-7 BRLS fl/hr, rec'd 131 BRLS 50/50 O&W, SI @ noon, plld thg & RTTS.

2-20-86 Acidz w/16,000gals 20% NEFE acid & 18,000gals glld wtr in 4 stages, max press 3550psi, avg press 3150psi, avg rate 36 RPM, ISIP 2700psi, 5min 2440psi, 10min 2400psi, 15min 2370psi, 1d 380 BRLS acid, 428 BRLS glld wtr, ttl 1188 BLW, flwd bck 250 BRLS, TIH w/thg & pkr, made 1 swb run, strt'd flwg, flwd until 6:00pm, died, SI, rec'd 350 BRLS.

I hereby certify that the foregoing is true and correct

SIGNED [Signature]

TITLE Drilling & Production Manager

DATE February 20, 1986

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

[Signature]

FEB 24 1986

CARISBAD, NEW MEXICO