Form	3160-5
June	19901

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TR	7. If Unit or CA. Agreement Designation	
Type or Well X Oil Gas Well Well Other		8. Well Name and No.
2 Name of Operator		Lea Unit No. 13
Marathon Oil Company		9 API Well No.
Address and Telephone No.		30-025-29381
P. O. Box 552, Midland, TX 79702		10. Field and Pool, or Exploratory Area
4 Location of Well (Footage, Sec., T., R., M., or Survey Description)		Lea (Bone Spring)
1980' FNL and 1980' FEL		1. County or Parish. State
Sec. 24, T20S, R34E		Lea Co., NM
CHECK APPROPRIATE BOX(s) TO I	NDICATE NATURE OF NOTICE.	REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF	ACTION
Notice of Intent		Change of Plans
	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	X Other Workover	Dispose Water

13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally druled give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work of

On 12/21/91, Marathon Oil Company initiated operations to perforate and fracture additional Bone Spring pay as follows:

(See attachment)

Tide Operations Engineer	Date2/26/92	
Tile	Date	
nue		
	Tide	

Ad

Pob ( 100)

Tide 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictuitious or fraudulent statement or representations as to any matter within its jurisdiction.

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

Completion or Recompletion Report and Log form.)

5. Lease Designation and Serial No.

ribe Name

	ľ	<u>0-M</u>	1747		
6.	If	Indian.	Allottee	or	Ŧ

## OCD HOBBS OFFICE

MAR 1 9 1992

## RECEIVED

Attachment to Form 3160-5 Lea Unit No. 13 Item 13

- 12/21/91 Test safety anchors to 22,500 psi. OK. MIRU Expert PU. Attempt to unseat pump. Found fiberglass rods parted 12 rods from surface. RIH w/overshot to fish 1.2" box. Catch rods, unseat pump & POOH w/rods & pump. ND wellhead. Unseat TAC. NU 6"-1500 series riserspool & 6" 1500 series hyd BOP's w/2 7/8" pipe rams & blind rams. Secured well. SDFN.
- 12/22/91 Open well. POOH w/2 7/8" N-80 tbg prod string. Replace sand line on PU. NU 7" WKM valve on BOP. RIH w/RBP on 4 stds tbg. Set RBP @ 250'. POOH w/tbg. Test BOP stack to 1000#. OK. Release & pull RBP. RIH w/10 stds tbg for kill string. SDFN.
- 12/23/91 Open well. Pump 50 bbls 2% KCl down tbg. POOH w/kill string. RU HLS Wireline. Test lub to 1000#. OK. Run 3 1/8" perf csg gun. Tag fillup @ 10,361'. Unable to get deep enough to perforate. POOH w/wireline. ND WKM valve. RIH w/4 5/8" bit on 2 7/8" tbg. Tag @ 10,376'. Rotate w/tbg tong. Drilled 5'. POOH w/45 jts. Secure well. SDFN.
- 12/24/91 Open well. (25,000 PPM H2s). Rig kill truck. Pump 50 Bbls. KCl wtr down csg. FIH w/2 7/8" tbg. Hot oil tbg w/70 Bbls oil. POOH leaving 10 stds for kill string. SDFN.
- 12/25/91 Shut down for Holidays.
- 12/26/91 Shut down for Holidays.
- 12/27/91 Kill well w/75 Bbls 2% Kcl wtr. POOH w/kill string. RIH w/4 5/8 bit on Bulldog Bailer on 2 7/8" tbg. Tag fillup @ 10,380'. Pig up power swivel. Rotate & drill scale to 10,534'. POOH Lay down Bailer. RIH w/10 stds tbg. SDFN.
- 12/28/91 POOH w/kill string. NU & test full lubricator to 1000#. OK. Perforate Bone Spring 10,468-10,491', 4 shots per ft w/3 1/8" csg gun. RD Perforators. RIH w/treating pkr on 2 7/8" 7.9# PH-6 P-110 tbg to 9300'. Secure well. SDFN.
- 12/29/91 Open well. RU Howco. Set pkr @ 9387'. Load annulus. Drop SV. Test tbg to 7000#. OK. PU SV. Psig annulus to 500#. <u>Acidize B. Spring</u> 9560-10,491' w/4000 gals 7 1/2" HCl w/132 B.S. AIR - 4 BPM @ 2200#. Good ball action. Cont pumping 3300 gals frac pad. Frac B.S. 10,468-10,491' w/29,000 gals gelled 2% KCl H20 w/42,700# 20-40 Ottowa sand. Flushed to top perfs w/2% KCl slick H20. AIR 15 BPM @ 5600 psi. Max psi 6000#. Min O#. ISIP 3042#. 5 min 2849#, 10 min 2765#, 15 min 2691#. RD Howco. SDFN.
- <u>12/30/91</u> 16 hr SITP 0#. Open well. Rig swab. RIH. BFL 1600' FS. Swab 10 hr. Rec 73 bbls. Load wtr. FFL 3700'. SDFN.
- 12/31/91 SITP 0#. Run swab. BFL 1800' FS. Rec 3 bbls wtr w/good show of oil. LD swab. Rel pkr. POOH. LD 299 jts 2 7/8" PW-6 workstring & pkr. RIH w/2 7/8" slotted mud anchor (16') 2 7/8" SN (1.10), 30 jts 2 7/8" N-80 tbg (931'), 2 7/8" Baker TAC (3') 80 jts 2 7/8" tbg (2496'). SDFN.

RECEIVED MAR 1 9 1992

.