Submit 3 Copies to Appropriate

State of New Mexico nerals and Natural Resources Department Energy,

Form C-103

Revised 1-1-89

| District Office | | ON DIVICION | | |
|--|--|--|---|--|
| DISTRICT I P.O. Box 1980, Hobbs, NM 88240 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 DISTRICT III 1000 Rio Brazos Rd., Azzec, NM 87410 | | | WELL API NO. 30-025-29459 | |
| | | | 5. Indicate Type of Lease STATE KX FEE | |
| | | | (i. State Oil & Gas Lease No. | |
| | TOTO AND DEPORTS ON M | /FILS | | |
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | | | 7. Lease Name or Unit Agreement Name | |
| 1. Type of Well: OB. GAS WELL X WELL | ОТНЕК | | South Hobbs (GSA) Unit | |
| 2. Name of Operator | | | 8. Well No. | |
| Amoco Production (| | | 9. Pool name or Wildcat | |
| 3. Address of Operator Attn: T P O Box 4891, House | | | Hobbs; Grayburg-San Andres | |
| 4. Well Location Unit Letter : 23 | 10 Feet From The Nort | h Line and 10 | 28 Feet From The East Line | |
| Section 6 | Township 9 | Range 38 suhar DF, RKB, RT, GR, etc.) | NIMPM Lea County | |
| 7////////////////////////////////////// | | | | |
| Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data | | | | |
| | Appropriate Box to Indica NTENTION TO: | SU | BSEQUENT REPORT OF: | |
| PERFORM REMEDIAL WORK | , | X REMEDIAL WORK | ALTERING CASING | |
| TEMPORARILY ABANDON | CHANGE PLANS | COMMENCE DRILLI | | |
| PULL OR ALTER CASING | | CASING TEST AND | CEMENT JOB — | |
| OTHER: | | OTHER: | | |
| 12. Describe Proposed or Completed Op | perations (Clearly state all pertinent des | ils, and give pertinent dates, in | cluding estimated date of starting any proposed | |
| work) SEE RULE 1103. | | | | |
| See attached proced | lure (Operations are s | cheduled to comme | ence approximately 11-01-96) | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| • | | | | |
| | _ | | | |
| | | | | |
| I hereby certify that the information above | se true/send complete to the best of my knowle | | 00/20/06 | |
| SIGNATURE | ulla | mre Sr. Busine | | |
| TYPE OR FRINT NAME TOM G. | Tullos | | TELEPHONE NO. 366-7337 | |
| | a martina de como de la composição de | | | |
| (This space for State Use) | ; | | OCT 64 1890 | |
| APPROVED BY | | TITLE | UAID | |
| CONDITIONS OF APPROVAL, IF ANY: | | | | |

Pertinent Data

Well: SHU PW 201 Flac No: 80883901

Field: SOUTH HOBBS / GRAYBURG-SAN AND/

Brief Date: 09/26/96

Workover Category: Flex

Radius of Exposure: 0' (500 ppm) & 0' (100 ppm);

Based on 0 mol % H2S

Engineer: David French

Home Phone: (713) 957-4892 SOCON: 321-4237 UserID: zdlf19 Mail Code: 17.130

Secretary: Cyndy Wright

SOCON: 321-7552

Work Objective: E - Change Status...PxA,TxA,convert, recomplete, return to prod. from

TXA

Symptoms: 36 - Marginal/Unprofitable well (verylow rate &/or offset oilcut)

Major Code: O - Other

Minor Codes:

Economics

Estimated Cost: \$ 12,000 (Gross)

General Comments

Production is not economic and well is currently shut-in. Final authorization pending partner and NMOCD approval. Salvage value of equipment estimated at \$3,000.

Procedure

Abandonment Procedure

- *** Verify original completion cement job placed sufficient cement behind production casing.
- 1) MIRUSU. (Notify NMOCD 24 hours prior to job)
- 2) RIH w/ Wkstring. Set CIBP at 3881'.
- 3) Cap CIBP w/ 25 sks class "C". Load hole w/ 9.5# brine.
- 4) Spot class C cmt plug 1530-1641'.
- 5) Cap x 10 sks class C cmt at surface.
- 6) Install PXA marker/cut off wellhead.

Engineer: Dave French (713) 366-4237