STALE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

| | | |
|--------------|-------------|--|
| | 1 | |
| DISTRIBUTION | | |
| BANTA FE | | |
| FILZ | | |
| U.S.O.S. | | |
| LAND OFFICE | | |
| SPERATOR | | |

OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103 -

| JANTA FE | SANTA FE, NEW MEXICO 87501 | Revised 10-1-73 |
|--|---|---|
| V.S.O.S. | | 5a, indicate Type of Lease |
| LAND OFFICE | | State X Foe |
| DETATOR | | 5. State OII & Gas Lease No. |
| | | |
| SUNDRY NOTICE | ES AND REPORTS ON WELLS HILL ON TO DEEPEN ON PLUG BACK TO A DIFFERENT RESERVOIR. MIT -" (FORM C-101) FOR SUCH PROPOSALS.) | |
| USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.) | | 7. Unit Agreement Nume |
| OIL GAB WELL OTHER- | _water injection | 7. Unit Agreement Nume |
| 2. Name of Operator | | 8. Farm or Lease Name |
| Amoco Production Company | | South Hobbs (GSA) Unit |
| Address of Operator D. O. Boy, 60, Hobbs, NM, 00040 | | 9. Well No. |
| P. O. Box 68 Hobbs, NM 882 | .40 | 215 |
| | UNIT LETTER E/D 1398/1000 FEET FROM THE NORTH LINE AND 1227/1250 | |
| UNIT LETTER | EET FROM THE HOT CIT LINE AND TELT FE | Hobbs (GSA) |
| West 4 | 19-S 38-E | |
| THE LINE, SECTION | TOWNSHIPRANGE | _nnon: {{ }}}} |
| | 15. Elevation (Show whether DF, RT, GR, etc.) | 12. County |
| | 3607.4' GR | Lea |
| Check Appropria | te Box To Indicate Nature of Notice, Report | or Other Data |
| NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: | | |
| | | |
| PERFORM REMEDIAL WORK | PLUG AND ABANDON REMEDIAL WORK | ALTERING CASING |
| TEMPORARILY ASAHOON | COMMENCE DAILLING OPHS. | PLUG AND ABANDONMENT |
| PULL OR ALTER CASING | CASING TEST AND CEMENT JOB OTHER Set produc | ction casing |
| OTHER | OTHER SEC PI OUL | ection casting |
| | | |
| 17. Describe Proposed or Completed Operations (Clauprk) SEE RULE 1103. | early state all pertinent details, and give pertinent dates, in | ncluding estimated dute of starting any proposed |
| • | | • |
| Deceled tetal death of 40401 | B ON EDO O B O O O | |
| Reached total depth of 4343'. | Run CNL FDC x Gamma Ray and Caliper. | $RIH_{W/5-1/2}$ " casing |
| stress Plug down at 10.22 n | Tool at 3821. Cement stage w/110 sam. 11-5-86. Cement second stage w/70 | acks class A and self |
| stress. Plug down at 2.23 a m | . and circulate. Release Cactus Rig | No. 5/ 11 6 96 No. |
| further report until completion | n. Wait on completion rig. | NO. 34 11-0-00. NO |
| • | | · |
| | | |
| | | |
| | | |
| | • | |
| - | , , | |
| | | |
| | | |
| | | |
| | | |
| 1 _ | | |
| | | |
| io. a negroy certify that the information above is true | and complete to the best of my knowledge and belief. | |
| Steve Brownlee | Admin. Analyst | 11-7-86 |
| AICHEO ALM LADIXED | TITLE TITLE | DATE |
| ORIGINAL SIGNED BY JEEPLY TEXT | GN | |
| DISTRICT : SUPENSIEUR | | 200 |
| CONDITIONS OF APPROVAL, IF ANY | YITLE | OATE TO THE TOTAL |
| | | _ |