

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-29771
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-3464-2
7. Lease Name or Unit Agreement Name	NORTH MONUMENT G/SA UNIT BLK. 4
8. Well No.	9
9. Pool name or Wildcat	EUNICE MONUMENT G/SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Amerada Hess Corporation	
3. Address of Operator P.O. DRAWER D. MONUMENT, NM 88265	
4. Well Location Unit Letter <u>I</u> : <u>1654</u> Feet From The <u>SOUTH</u> Line and <u>330</u> Feet From The <u>EAST</u> Line Section <u>24</u> Township <u>19S</u> Range <u>36E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: CONVERT TO INJECTION WELL. ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #409 (01-06-97 THRU 01-10-97)

PRIDE WELL SVC. & STAR TOOL MIRU. PUMPED 70 BBLS. WATER TO KILL CSG. & BLED DWN. TBG. UNSEATED PUMP & KILLED TBG. W/35 BBLS. WATER. TOH W/PROD. EQUIP. ND WELLHEAD & INSTALLED BOP. TOH W/TBG. SUBS. 119 JTS. TBG., 1 JT. SALTA & 2-3/8" SN. TIH W/RBP. SN & 119 JTS. TBG. SET & GOT OFF RBP @ 3,855'. DISPLACED & CIRC. WELLBORE W/100 BBLS. W/9.5# BRINE WATER. CIRC. WELL CLEAN. LOADED SURF. CSG. W/WATER & PRESS'D. CSG. TO 500#. TOH W/21 JTS. TBG. RETRIEVING HEAD @ 3,195'. SLURRED & PUMPED 2 SKS. SAND TO COVER RBP. CIRC. WELLBORE CLEAN OF MIGRATING OIL. TOH W/98 JTS. TBG., SN. & RETRIEVING HEAD. ND BOP & ADAPTER FLANGE. LOADED 5-1/2" CSG. W/WATER. RMV'D. OLD WELLHEAD & INSTALLED NEW ONE. PRESS. TST'D. WELLHEAD TO 2,500#. HELD. NU BOP. PRESS. TST'D. CSG. TO 580# & CHARTED 30 MIN. TST. CSG. HELD.
(CONTINUED)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE SR. STAFF ASSISTANT DATE 01/14/97
TYPE OR PRINT NAME TERRY L. HARVEY TELEPHONE NO. 505-393-2144

(This space for State Use)

ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE AUG 07 1997

CONDITIONS OF APPROVAL, IF ANY:

ICB