

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-29771
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-3464-2
7. Lease Name or Unit Agreement Name	NORTH MONUMENT G/SA UNIT BLK. 4
8. Well No.	9
9. Pool name or Wildcat	EUNICE MONUMENT G/SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER INJECTION	
2. Name of Operator Amerada Hess Corporation	
3. Address of Operator P.O. DRAWER D, MONUMENT, NM 88265	
4. Well Location Unit Letter <u>I</u> : <u>1654</u> Feet From The <u>SOUTH</u> Line and <u>330</u> Feet From The <u>EAST</u> Line Section <u>24</u> Township <u>19S</u> Range <u>36E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: CONVERT TO INJECTION WELL. ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #409

MIRU PULLING UNIT & REVERSE UNIT. TOH & LAY DWN. RODS & PUMP. ND WELLHEAD. NU BOP. TOH W/TBG. TIH W/RBP & SET @ +/-500'. INSTALL NEW WELLHEAD EQUIP. TIH W/TBG. & RETRIEVE RBP. TOH W/RBP. TIH W/4-3/4" BIT. D.C.'S & TBG. CLEAN OUT TO TD @ 3,955'. DRILL 20' NEW HOLE TO 3,975'. TOH W/BIT. RU SCHLUMBERGER & LOG THE O.H. W/SONIC/CNL/GR/CCL TOOLS. TIH W/4" CSG. GUN. SELECTIVELY PERF. 3,834'-3,940', 2 JSPF, 180 DEG. PHASED HEG CHGS. RD SCHLUMBERGER. TIH W/SONIC HAMMER ON TBG. TO TD. RU ACID CO. ACIDIZE WELL W/4,000 GALS. 15% NEFE DI HCL W/1.5% DP-77MX MICELLAR SOLVENT. TOH W/SONIC HAMMER. TIH W/TBG. & PKR. SET PKR. @ +/-3,650'. SWAB/FLOW BACK LOAD. TOH W/TBG. & PKR. LAYING DWN. PROD. TBG. PU & TIH W/2-3/8 LINED INJ. TBG. W/INJ. PKR. ND BOP. NU INJ. WELLHEAD ASSEMBLY. RDMO PULLING UNIT. CLEAN & CLEAR LOCATION. OBTAIN SI BTM. HOLE PRESS. BEFORE BEGINNING INJECTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE SR. STAFF ASSISTANT DATE 08/19/96
TYPE OR PRINT NAME TERRY L. HARVEY

TELEPHONE NO. 505-393-2144

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE AUG 20 1996
CONDITIONS OF APPROVAL, IF ANY: