

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator Crown Central Petroleum Corporation		8. Farm or Lease Name Oriole	
3. Address of Operator 4000 N. Big Spring, Suite 213, Midland, TX 79705		9. Well No. 1	
4. Location of Well UNIT LETTER <u>H</u> <u>1650</u> FEET FROM THE <u>North</u> LINE AND <u>990'</u> FEET FROM THE <u>East</u> LINE, SECTION <u>28</u> TOWNSHIP <u>19-S</u> RANGE <u>38-E</u> NMPM.		10. Field and Pool, or Wildcat Nadine (Drinkard-Abo)	
15. Elevation (Show whether DF, RT, GR, etc.) 3583.7 GR		12. County Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-13-87 Spud well at 11:30 P.M. - 2-13-87

2-16-87 T.D. 1560'. Run 8-5/8" csg. to 1560'. Cement with 600 sacks Western Lite with 3% salt. Tail in with 200 sack Class "C". Circ. 280 sks. to surface. Bump plug with 900 psig.

2-17-87 Drill out float collar and test casing to 1000# for 15 min.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED L.R. Belden L.R. Belden TITLE Petroleum Engineer DATE 2-17-87

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR
APPROVED BY JERRY SEXTON TITLE DISTRICT 1 SUPERVISOR DATE FEB 20 1987

CONDITIONS OF APPROVAL, IF ANY: