

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

**DISTRICT I**  
P.O. Box 1980, Hobbs NM 88241-1980

**DISTRICT II**  
P.O. Drawer DD, Artesia, NM 88210

**DISTRICT III**  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO.  
30-025-30027

5. Indicate Type of Lease  
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name  
Emerald

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator  
Cross Timbers Operating Company

8. Well No.  
1

3. Address of Operator  
3000 N. Garfield, Suite 175 Midland, Texas 79705

9. Pool name or Wildcat  
Nadine; Drinkard, East

4. Well Location  
Unit Letter P : 990 Feet From The South Line and 990 Feet From The East Line

Section 25 Township 19S Range 38E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
GR 3575.6'; RKB 3591'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 8200', CIBP @ 7131' (PBDT). Casing as follows: 13-3/8" @ 203', cmt'd w/ 210 sx cmt; 8-5/8" @ 1558', cmt'd w/810 sxs and 5-1/2" @ 8199' (DV Tool @ 5043'), cmt'd w/2200 sx cmt. TOC @ 3300'. CTOC proposes to MI & RU well service unit. POH w/tubing, rods and pump. RU wireline truck & set CIBP @ 6930'. Dump bail 35' cmt cap on top of plug. WO cement. RIH w/tbg open ended & tag cmt cap @ approx. 6895'. Circ hole w/salt gel mud (9.5# brine w/25# of gel/bbl. Pull up hole to 6600' & spot 25 sx cmt plug from 6600-6500', spot 25 sx cmt plug from 5093-4993'. Run free point survey and cut 5-1/2" casing @ approx 3000'. POH & LD csg. RIH w/tbg open ended to 3050'. Spot 25 sx cmt plug from 3050-2950'. WO cmt & tag plug. Spot 25 sx cmt plug from 1800-1700', spot 25 sx cmt plug from 1609-1509'. WO cmt & tag plug. Spot 25 sx cmt plug from 253-153'. WO cmt & tag plug. Spot a 10 sx cmt plug @ surface. Install P & A marker. RD & MO unit. Dig up & cut off anchors. Clean location.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Janice Courtney TITLE Regulatory Tech DATE 5/27/99  
TYPE OR PRINT NAME Janice Courtney TELEPHONE NO. 915/682-8873

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

✓  
MP