

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-30063
5. Indicate Type of Lease	STATE ☒ FEE
6. State Oil / Gas Lease No.	B 5943
7. Lease Name or Unit Agreement Name	MONSTATE
8. Well No.	6
9. Pool Name or Wildcat	EUMONT YATES 7 RIVERS QUEEN (PRO GAS)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.	
1. Type of Well:	OIL WELL ☐ GAS WELL ☒ OTHER ☐
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>J</u> : <u>1980</u> Feet From The <u>SOUTH</u> Line and <u>1750</u> Feet From The <u>EAST</u> Line Section <u>13</u> Township <u>19S</u> Range <u>36E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3717'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
 PULL OR ALTER CASING ☐
 OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
 COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
 CASING TEST AND CEMENT JOB ☐
 OTHER: ☐ RECOMPLETE IN EUMONT -TA ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-16-01: MIRU KEY. ND TREE. NUBOP. TIH W/BIT, CSG SCRAPER ON WS & TAG @ 6821'. DISPL HLE W/260 BBLS 2% KCL WTR. STOP BIT @ 1584'.
 4-17-01: TIH W/CMT BAILER. DUMP 25' CMT ON CIBP. WOC 4 HRS. TIH W/GR & CCL. TAG @ 6795'. LOG 6795-6600. TIH W/CIBP & SET @ 6725'. TA DRINKARD. TIH W/CMT BAILER & DUMP 35' CMT ON CIBP.
 4-18-01: TIH W/GR & CCL & TAG CMT ON TOP OF CIBP @ 6690'. TIH W/CIBP #2 & SET @ 5100'. TA LOWER SAN ANDRES. TIH W/CMT BAILER & DUMP 35' CMT ON CIBP. TIH W/GR-CCL & TAG CMT @ 5063'. TIH W/CIBP #3 & SET @ 4175'. TA UPPER SAN ANDRES. TIH W/CMT BAILER & DUMP 35' CMT ON CIBP.
 4-19-01: TIH W/GR-CCL TAG CMT @ 4138'. TIH W/PERF GUN & PERF EUMONT FORMATION, 3680-3700. TIH W/GUN & PERF 3650-52, 3662-64. ALL GUNS FIRED. SHOT OUT OF ZONE 3622-24, 3625-33, 3643-47. TIH W/GUN & PERF 3610-12, 3622-30, 3634-38. TIH W/PKR, & SN ON TBG. SET PKR @ 3536'. LOAD & TEST BACKSIDE TO 500#-OK. ACIDIZE EUMONT PERFS 3610-3700 W/2000 GALS 15% NEFE HCL.
 4-20-01: RU SWAB. TIH TO SN @ 3576'. NO GAS SHOW. UNSET PKR & RESET @ 3598'. FL @ 3300. SWAB DRY. REL PKR. TIH W/FAC PKR, SN ON FRAC TBG. TEST TO 8000#. PKR SWINGING @ 1089'.
 4-21-01: TIH W/WS. RAN 111 JTS 3 1/2" FRAC TBG. TEST TO 8000#. SET PKR @ 3505'. INSTL FRAC TREE ON TOP OF BOP. LOAD & TEST BACKSIDE TO 500#-OK.
 4-23-01: FRAC EUMONT PERFS 3610-3700 W/53,333 GALS 30# X-LINK GEL. FLOWBACK.
 4-30-01: UNECONOMICAL. KILL TBG. ND FRAC TREE. LD FRAC TBG. TIH W/CIBP & SET 50' ABOVE EUMONT EPRFS @ 3560'. TIH W/CMT BAILER & DUMP 35' CMT ON CIBP. PBD-3525. TIH W/TBG OPEN ENDED TO 1580'.
 5-01-01: TIH W/TBG. TAG CMT @ 3535-OK. DISPL HLE W/150 BBLS PKR FLUID. TEST & CHART CSG & CIBP TO 500#-30 MINS FOR NMOC-D-OK. LD 218 JTS 2 7/8" WS. NDBOP & NU TREE. RIG DOWN.
 STATUS IS TEMPORARILY ABANDONED. FINAL REPORT

This Approval of Temporary
Abandonment Expires

10/17/06

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 5/30/01

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL IF ANY: TITLE

DATE 10/17/06

DeSoto/Nichols 12-93 ver 1.0



