

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-77

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State ☒ Fee ☐  
5. State Oil & Gas Lease No.  
B-5943

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Texaco Producing Inc.	8. Farm or Lease Name Monstate <del>TH</del>
3. Address of Operator P.O. Box 728, Hobbs, New Mexico 88240	9. Well No. 6
4. Location of Well UNIT LETTER J 1980 FEET FROM THE South LINE AND 1750 FEET FROM East 13 TOWNSHIP 19S RANGE 36E NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3735' KB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOBS ☐ Completion attempts ☒  
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

- 12-10-87 Perforated Wolfcamp from 8398-8461'. Acidized with 5000 g. acid. Recovered 0 BO and 225 BW swabbing 10 hrs. Set cement retainer at 8390' and squeezed perms w/100 sxs. Perfs abandoned.
- 12-15-87 Perforated Wolfcamp from 8322-8386'. Recovered 0 BO and 152 BW swabbing 10 hrs. Set CIBP @ 8310' and capped with 35' cmt. PBTD 8275'. Wolfcamp abandoned.
- 12-24-87 Perforated Abo from 7974-8010'. Acidized with 5500 g. acid. Recovered 0 BO and 111 BW swabbing for 6 hrs. Set cement retainer at 7964'. Squeezed perms w/100 sxs. Abo perfs abandoned.
- 1-14-88 Perforated Abo from 7628-7950'. Acidized w/10,000 g. acid. Recovered trace of oil and 9 BW swabbing for 4 hrs. Set CIBP @ 7625' and capped with 10' cement. PBTD 7615'; Abo perfs abandoned.
- 1-25-88 Perforated Abo from 7238-7605'. Acidized with 10,000 g. acid. Recovered trace of oil and 128 water with a trace of gas swabbing 9.5 hrs. Set CIBP @ 7250' and capped with 35' cement.; Abo perfs abandoned. Set CIBP @ 6850' and capped with 10' cement. PBTD 6840'.
- 2-1-88 Perforated San Andres from 5129-5162'. Recovered 0 BO and 97 BW swabbing 10 hrs. Set CIBP @ 5100' & capped with 35' cement. PBTD 5065'. Perfs abandoned. (OVER)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

397-3571

SIGNED Ja Huan TITLE Hobbs Area Superintendent DATE 10-31-88

Orig. Signed by  
Paul Kautz  
Geologist

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

TA expires 11-1-89

2-10-88 Perforated from 4200' to 4367'. Recovered trace of oil and 36 bbls water with trace of gas swabbing for 6 hours. Shut well in to evaluate for shallower recompletion attempt.

RECEIVED

NOV 2 1988

OCO

HOLD ON