

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
En , Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30534
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V 1618
7. Lease Name or Unit Agreement Name New Mexico FH State Com.
8. Well No. 1
9. Pool name or Wildcat Salt Lake Morrow South

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator Exxon Corporation
3. Address of Operator P.O. Box 1600, Midland, TX 79702	4. Well Location Unit Letter <u>F</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>1420</u> Feet From The <u>West</u> Line Section <u>32</u> Township <u>20S</u> Range <u>33E</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3616 GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-23-89 NU BOPs and test to 5000#.  
12-24-89 Set CIBP @ 12500' and test to 500#.  
12-26-89 Spot 15 sxs CLH on CIBP and displace hole w/ 10 ppg salt mud.  
Spot 25 sxs CLH from 12375' - 12175'.  
Spot 25 sxs CLH from 11360' - 11160'.  
Spot 25 sxs CLH from 8390' - 8190'.  
12-28-89 Cut off csg @ 6560'.  
12-30-89 Spot 55 sxs CLH from 6660' - 6479'. Tagged at 6479'.  
Spot 70 sxs CLC from 5000' - 4350'. Tagged at 4350'.  
Spot 70 sxs of CLC at 3600'.  
Pump 1110 sxs of Salt cmt. from 3200' to surface.  
Cut off wellhead, install dry hole marker and clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE D. Johnson TITLE Administrative Specialist DATE 1-4-90  
TYPE OR PRINT NAME Stephen Johnson (915) 688-7548 TELEPHONE NO.

(This space for State Use)

APPROVED BY R. A. Ladd OIL & GAS INSPECTOR DATE MAY 7 1990  
CONDITIONS OF APPROVAL, IF ANY: