

Submit 5 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-30534
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	V 1618
7. Lease Name or Unit Agreement Name	New Mexico FH State Com.
8. Well No.	1
9. Pool name or Wildcat	Salt Lake Morrow South
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3616 GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
Exxon Corporation

3. Address of Operator
P.O. Box 1600, Midland, TX 79702

4. Well Location
Unit Letter F : 1980 Feet From The North Line and 1420 Feet From The West Line
Section 32 Township 20S Range 33E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Exxon requests permission to Temporarily Abandon the above captioned well.

Test anchors, NU BOPs and test, POOH w/ PKR.
Set cement retainer @ 12,575 and test. Pump 25 sxs to sqz perfs 12,596-12,609.
Spot 10 sxs on top of cement retainer. Displace hole w/ corrosion inhibitor and bactericide. Leave 1000' to 2 7/8" tbq in hole.
Clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

D. Johnson

TITLE

Administrative Specialist 12-19-89

DATE

TYPE OR PRINT NAME

Stephen Johnson

(915) 688-7548

TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY

DISTRICT I SUPERVISOR

TITLE

DATE

DEC 22 1989

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

DEC 21 1989

OCD
HOBBS OFFICE