

Submit 3 Copies
Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

STRICT I
Box 1980, Hobbs, NM 88240

STRICT II
Drawer DD, Artesia, NM 88210

STRICT III
Box Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-025-30930

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
E-1638

7. Lease Name or Unit Agreement Name

Fina State

8. Well No.

9. Pool name or Wildcat

Pearl Queen-Seven Rivers

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS

Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator
Xeric Oil & Gas Company

Address of Operator
P.O. Box 51311, Midland, TX 79710

Well Location
Unit Letter L : 1650 Feet From The South Line and 330 Feet From The West Line

Section 31 Township 19-S Range 35-E NMPM 1 County Lea

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

GL-3707

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WORK ☐ ALTERING CASING ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐ CASING TEST AND CEMENT JOB ☐
OTHER: ☐ OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The subject well has 8 5/8" Surface Casing set at 1815' cemented to surface and 5 1/2" casing set at 5000'. Top of cement is estimated to be at 2958' from surface. Plugging is anticipated to begin immediately upon approval of procedure.

1. Move in and rig-in pulling unit. Pull 2 3/8 tubing out of hole.
2. Set CIPB at approx 4750 (top of Penrose). Cap w/ 35 sx cement.
3. Set 15 sx cement plug at surface.
4. Install dry hole marker.

WILL NEED TO PERF OR PULL 5 1/2" FROM,
ABOVE TOP OF SALT & PLACE ~~500'~~ 100' PLUG OUTSIDE & INSIDE
OF PIPE

I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE G. S. Barker TITLE Operations Manager DATE 9/16/91

TYPE OR PRINT NAME Gary S. Barker

TELEPHONE NO. 915-683-31

(This space for State Use)

APPROVED BY Gary S. Barker TITLE Operations Manager DATE 9/16/91
CONDITIONS OF APPROVAL, IF ANY: APPROVAL MUST BE NOTICED 24 HOURS BEFORE THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.