

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

CHEVRON USA INC

3. Address and Telephone No.

P.O. Box 1150 Midland TX 79702 ATTN: RM 4111

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

560 FSL & 660 FWL

SEC 14 T20S R36E Unit M

5. Lease Designation and Serial No.

NM-1151

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

EUNICE Monument
South Unit-B

8. Well Name and No.

887

9. API Well No.

30-025-31126

10. Field and Pool, or Exploratory Area

EUNICE Monument/GSA

11. County or Parish, State

LEA NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other Completion Summary
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRU Perf w/4" guns f/4322-4325' 4 JHPF 12 holes .5 dia. 180° phasing SWAB ACD'2 perf w/2319 gals 15% NEFE Perf f/4140-4160' 2 JHPF 40 holes ACD'2 perf 414-60' w/2000 gals 15% NEFE SWAB Perf f/4096-4112' w/4" guns 1/2" holes 32 holes 180° phasing ACD'2 w/2000 gals 15% NEFE SWAB TIH SET RBP @ 4250' DUMP 53x SAND ON RBP TAG SD @ 4235' SET CICK @ 4020' PUMPED 150 sx C' REV. OUT 89 sx. WOC TAG CMT @ 3943' Delg CMT f/3943'-4118' C/O 28' SD f/4225-4248'. Tst sg2 to 500 ps. OK. Perf f/4205-10' 180° phasing .5 dia. 10 Holes. ACD'2 w/420 gals 15% NEFE. SWAB. MOVE RBP up hole to 4150' Perf f/4096-4112' 2 JHPF 180° phasing 32 holes total. ACD'2 w/500 gals 15% NEFE Perf f/4140-60 10 holes 180° phasing Perf f/3888-4080' 2 JHPF 92 Total Holes. TOH w/ PKR & RBP TIH SET RBP @ 4088' + SET PKR @ 3950' ACD'2 w/6900 gals 15% OVER →

14. I hereby certify that the foregoing is true and correct

Signed E. O. Anthony

Title T.A. Delg

Date 4/16/91

(This space for Federal or State office use)

Approved by
Conditions of approval, if any:

Title

Date

NEFE HCL SWAB BACK. TOH W/ PKR + RBP PERF F/ 3832' - 3958'
2 JHPF TOTAL OF 70 HOLES SET RBP @ 3860' ACD'Z W/ 5250 GALS 15% NEFE
SWAB BACK TOH W/ PKR + RBP RUN PRODUCTION EQUIPMENT TURN
OVER TO PRODUCTION.

WORK STARTED 3/24/91

ENDED 4/16/91