

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.  
30-025-31505

5. Indicate Type of Lease  
STATE  FEE

6. State Oil & Gas Lease No.  
B-6114



7. Lease Name or Unit Agreement Name  
NORTH MONUMENT G/SA UNIT  
BLK.11

8. Well No.  
18

9. Pool name or Wildcat  
EUNICE MONUMENT G/SA

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL  GAS WELL  OTHER

2. Name of Operator  
Amerada Hess Corporation

3. Address of Operator  
P.O. DRAWER D, MONUMENT, NM. 88265

4. Well Location  
Unit Letter B : 1500 Feet From The EAST Line and 1260 Feet From The NORTH Line  
Section 29 Township 19S Range 37E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)



11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

<b>NOTICE OF INTENTION TO:</b>		<b>SUBSEQUENT REPORT OF:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <u>CONVERT TO WATER SUPPLY WELL</u> <input checked="" type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #1118

TOH WITH PRODUCTION EQUIPMENT. CEMENT SQUEEZE GRAYBURG PERFS. 3,820'-3,955'. DRILL OUT RETAINERS AND SQUEEZE CEMENT INCLUDING RETAINER AND CEMENT FROM 3,977'-4,011'. CLEAN OUT TO TD AT 5,147'. PERFORATE THE SAN ANDRES FROM 4,390'-4,070'. ACIDIZE NEW PERFS WITH 15,000 GALS. 15% NEFE HCL. SWAB BACK ACID LOAD. RUN SUBMERSIBLE PUMP AND TEST PUMP WELL.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE SR. STAFF ASSISTANT DATE 01-30-96

TYPE OR PRINT NAME TERRY L. HARVEY TELEPHONE NO. 505-303-2144

(This space for State Use) ORIGINAL SIGNED BY JERRY BEKTON  
DISTRICT I SUPERVISOR

FEB 6 1996

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

