

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-31587
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-1167-48
7. Lease Name or Unit Agreement Name	NORTH MONUMENT G/SA UNIT BLK. 14
8. Well No.	19
9. Pool name or Wildcat	EUNICE MONUMENT G/SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Amerada Hess Corporation	
3. Address of Operator P.O. DRAWER D. MONUMENT, NM 88265	
4. Well Location Unit Letter C : 80.5 Feet From The NORTH Line and 1505 Feet From The WEST Line Section 36 Township 19S Range 36E NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #1419 (01-28-97 THRU 01-30-97)

TYLER WELL SVC. MIRU. PULLED PROD. EQUIP. RAN A BIT ON 124 JTS. OF 2-7/8" TBG. & TAGGED BTM. @ 3,944' FOR NO FILL. TOH W/TBG. & BIT. RAN SONIC HAMMER ON 117 JTS. OF TBG. TO 3,744'. KNOX SVCS. PUMPED 150 BBLs. FW @ 5.3 BPM & 550# TBG. PRESS. CSG. PRESS. VACUUM. WASHED THE 7" CSG. PERFS. FR. 3,747'-3,943' W/THE SONIC HAMMER. PUMPED 4,500 GALS. OF 15% NEFE DI ACID W/1.5% KS-SOL CHEMICAL @ 6.3 BPM & 1,740# TBG. PRESS. CSG. ON VACUUM. ACIDIZED THE 7" CSG. PERFS. FR. 3,747'-3,943' W/THE SONIC HAMMER. FLUSHED W/66 BBLs. FW. DROPPED A BALL & OPENED THE SHEAR SLEEVE ON THE SONIC HAMMER. SWABBED WELL. JARREL SVCS. RAN A BHP GAUGE TO DATUM @ 3,877'. CHK'D. BHP. WELL STABILIZED. TOH W/TBG. & SONIC HAMMER. RAN A 2-7/8" SN ON 1 JT. OF 2-7/8" IPC LINED TBG., 6 JTS. OF 2-7/8" TBG., A 7" X 2-7/8" TAC & 115 JTS. OF 2-7/8" TBG.
(CONTINUED)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE SR. STAFF ASSISTANT DATE 01-31-97
TYPE OR PRINT NAME TERRY L. HARVEY TELEPHONE NO. 505-393-2144

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: _____