State Lease - 6 copies Fee Lease - 5 copies	Energy	State of New 1 y, Minerals and Natural	Resources Department		Form C-101 Revised 1-1-89
DISTRICT P.O. Box 1980, Hobbs, 1	OIL	CONSERVATI		API NO. (assigned by O	CD on New Wells
P.O. Box 1980, Hobbs, NM 88240 <u>DISTRICT II</u> P.O. Box 2088 Santa Fe, New Mexico 87504-2088				30-02	5-31593
P.O. Drawer DD, Artesia	, NM 88210		0150+2088	5. Indicate Type of Leas	ж
DISTRICT III					TATE X FEE
1000 Rio Brazos Rd., Aziec, NM 87410				6. State Oil & Gas Leas B-1167	e No.
APPLICATION FOR PERMIT TO DRILL, DEEPEN, OR PLUG BACK					mmmm
ia. Type of work:				7. Lease Name or Unit	Agreement Name
DRI b. Type of Weil:	LL X RE-ENTE	R DEEPEN	PLUG BACK		
OL GAS	X OTHER	SINGLE			
2. Name of Operator		Z ONE		Shell State	("B")
-	Owens Petroleum,	Tra		8. Well No.	
3. Address of Onemice		9. Pool name or Wildcat	1		
	P.O. Box 2911,	Midland, Texas	79702		e D
4. Well Location	0.000			Eumont y	Dr-GN
Unit Letter	C: <u>990</u> Feet F	rom The North	Line and 1980) Feet From The	West Lin
Section 3	6 _	thin 19-S)(p		
	Towns	ship ¹ , ⁰ Ri	unge 36-E 1	NMPM Lea	County
		10. Proposed Depth	11. F	ormation	
			0000	es/7 Rivers/Queen	12. Rotary or C.T. 1 Rotary
3. Elevations (Show wheth 3602' Ground Le		4. Kind & Status Plug. Bond Single-well	15. Drilling Contractor	16 Anomy	Date Work will start
7.			McGee Drillin	ng #1 5/6/92	
SIZE OF HOLE	PR SIZE OF CASINO	OPOSED CASING A			
	SIZE OF CASING	WEIGHT PER FOOT	SETTING DEPTH	SACKS OF CEMENT	FOT TOP
$12\frac{1}{4}$ "	9 5/8"	40 04	100.		EST. TOP
<u> 12¼" </u>	<u> </u>	<u>40.0#</u> 23.0#	400'	sufficient to ci	rculate
		40.0# 23.0#			rculate
8 3/4"	7"	23.0#	3800 '	sufficient to ci sufficient to ci	rculate
8 3/4" A 12¼" hole wil	1 be drilled to	23.0# 400' using fres	3800' Nwater. 9 5/8"	sufficient to ci sufficient to ci casing will be	rculate rculate
8 3/4" A 12¼" hole wil to surface. Dri through the res	1 be drilled to 11 out from unde	400' using fresher surface with a	3800' 1 water. 9 5/8" 20 8 3/4" bit us	sufficient to ci sufficient to ci casing will be ing 10 ppg brine	rculate rculate set and cemente
8 3/4" A 12¼" hole wil to surface. Dri through the res	1 be drilled to 11 out from unde	400' using fresher surface with a	3800' 1 water. 9 5/8" 20 8 3/4" bit us	sufficient to ci sufficient to ci casing will be ing 10 ppg brine	rculate rculate set and cemente
8 3/4" 12¼" hole wil o surface. Dri hrough the res tarch, MW - 10	7" 1 be drilled to 11 out from unde erve pit. At 240 .0 to 10.1, flui	23.0# 400' using fres er surface with a 00', the system w id loss of 6 cc o	3800' n water. 9 5/8" an 8 3/4" bit us yill be mudded u or less. Continu	sufficient to ci sufficient to ci casing will be ing 10 ppg brine p through the re e drilling to PT	rculate rculate set and cemente , circulating serve pit with
8 3/4" 12¼" hole wil o surface. Dri hrough the res tarch, MW - 10 f commercial s	7" 1 be drilled to 11 out from unde erve pit. At 240 .0 to 10.1, flui	23.0# 400' using frest er surface with a 00', the system w id loss of 6 cc o	3800' n water. 9 5/8" an 8 3/4" bit us vill be mudded u or less. Continue	sufficient to ci sufficient to ci casing will be ing 10 ppg brine p through the re e drilling to PT	rculate rculate set and cemente , circulating serve pit with
8 3/4" A 12¼" hole wil to surface. Dri hrough the res starch, MW - 10 f commercial s	7" 1 be drilled to 11 out from unde erve pit. At 240 .0 to 10.1, flui	23.0# 400' using frest er surface with a 00', the system w id loss of 6 cc o	3800' n water. 9 5/8" an 8 3/4" bit us vill be mudded u or less. Continue	sufficient to ci sufficient to ci casing will be ing 10 ppg brine p through the re e drilling to PT	rculate rculate set and cemente , circulating serve pit with
8 3/4" 12¼" hole wil o surface. Dri hrough the res tarch, MW - 10 f commercial s	7" 1 be drilled to 11 out from unde erve pit. At 240 .0 to 10.1, flui	23.0# 400' using fres er surface with a 00', the system w id loss of 6 cc o	3800' n water. 9 5/8" an 8 3/4" bit us vill be mudded u or less. Continue	sufficient to ci sufficient to ci casing will be ing 10 ppg brine p through the re e drilling to PT	rculate rculate set and cemente , circulating serve pit with
8 3/4" A 12¼" hole wil to surface. Dri hrough the res starch, MW - 10 f commercial s	7" 1 be drilled to 11 out from unde erve pit. At 240 .0 to 10.1, flui	23.0# 400' using frest er surface with a 00', the system w id loss of 6 cc o	3800' n water. 9 5/8" an 8 3/4" bit us vill be mudded u or less. Continue	sufficient to ci sufficient to ci casing will be ing 10 ppg brine p through the re e drilling to PT	rculate rculate set and cemente , circulating serve pit with
8 3/4" A 12¼" hole wil to surface. Dri hrough the res starch, MW - 10 f commercial s	7" 1 be drilled to 11 out from unde erve pit. At 240 .0 to 10.1, flui	23.0# 400' using frest er surface with a 00', the system w id loss of 6 cc o	3800' n water. 9 5/8" an 8 3/4" bit us vill be mudded u or less. Continue	sufficient to ci sufficient to ci casing will be ing 10 ppg brine p through the re e drilling to PT	rculate rculate set and cemente , circulating serve pit with
8 3/4" A 12¼" hole wil to surface. Dri hrough the res starch, MW - 10 f commercial s	7" 1 be drilled to 11 out from unde erve pit. At 240 .0 to 10.1, flui	23.0# 400' using frest er surface with a 00', the system w id loss of 6 cc o	3800' n water. 9 5/8" an 8 3/4" bit us vill be mudded u or less. Continue	sufficient to ci sufficient to ci casing will be ing 10 ppg brine p through the re e drilling to PT	rculate rculate set and cemente , circulating serve pit with
8 3/4" 12¼" hole wil o surface. Dri hrough the res tarch, MW - 10 f commercial s o surface. If	7" 1 be drilled to 11 out from unde erve pit. At 240 .0 to 10.1, flui hows are present a dry hole, prop	23.0# 400' using fresh er surface with a 00', the system w id loss of 6 cc o c, 7" production per plugs will be	3800' n water. 9 5/8" an 8 3/4" bit us vill be mudded u or less. Continue casing will be s set as directed	sufficient to ci sufficient to ci casing will be ing 10 ppg brine p through the re e drilling to PT set at 3800' and d by the NMOCD.	rculate rculate set and cemente , circulating serve pit with D of 3800'. cemented back
8 3/4" A 12¼" hole wil to surface. Dri hrough the res tarch, MW - 10 f commercial s o surface. If N ABOVE SPACE DESC ONE OVE BLOWOUT PREVEN	7" 1 be drilled to 11 out from unde erve pit. At 240 .0 to 10.1, flui hows are present a dry hole, prop RIBE PROPOSED PROGRA	400' using fres er surface with a 00', the system w id loss of 6 cc c c, 7" production ber plugs will be	3800' n water. 9 5/8" an 8 3/4" bit us yill be mudded u or less. Continue casing will be a set as directed	sufficient to ci sufficient to ci casing will be ing 10 ppg brine p through the re e drilling to PT set at 3800' and d by the NMOCD.	rculate rculate set and cemente , circulating serve pit with D of 3800'. cemented back
8 3/4" A 12¼" hole wil to surface. Dri hrough the res tarch, MW - 10 f commercial s o surface. If N ABOVE SPACE DESC ONE OVE BLOWOUT PREVEN	7" 1 be drilled to 11 out from unde erve pit. At 240 .0 to 10.1, flui hows are present a dry hole, prop RIBE PROPOSED PROGRA	23.0# 400' using fresh er surface with a 00', the system w id loss of 6 cc o c, 7" production per plugs will be	3800' n water. 9 5/8" an 8 3/4" bit us yill be mudded u or less. Continue casing will be a set as directed	sufficient to ci sufficient to ci casing will be ing 10 ppg brine p through the re e drilling to PT set at 3800' and d by the NMOCD.	rculate rculate set and cemente , circulating serve pit with D of 3800'. cemented back
8 3/4" A 12¼" hole wil to surface. Dri hrough the res tarch, MW - 10 f commercial s o surface. If N ABOVE SPACE DESC ONE OVE BLOWOUT PREVEN	7" 1 be drilled to 11 out from unde erve pit. At 240 .0 to 10.1, flui hows are present a dry hole, prop RIBE PROPOSED PROGRA	400' using fres er surface with a 00', the system w id loss of 6 cc c c, 7" production ber plugs will be	3800' n water. 9 5/8" an 8 3/4" bit us yill be mudded u or less. Continue casing will be s set as directed OR FLUG BACK, GIVE DATA ON P	sufficient to ci sufficient to ci sufficient to ci casing will be ing 10 ppg brine p through the re e drilling to PT set at 3800' and d by the NMOCD.	rculate rculate set and cemente , circulating serve pit with D of 3800'. cemented back
8 3/4" A 12¼" hole will to surface. Dri through the res tarch, MW - 10 f commercial s o surface. If N ABOVE SPACE DESC ONE. GIVE BLOWOUT PREVEN hereby certify that the information on ATURE	7" 1 be drilled to 11 out from unde erve pit. At 240 .0 to 10.1, flui hows are present a dry hole, prop RIBE PROPOSED PROGRA	400' using fres er surface with a 00', the system w id loss of 6 cc c c, 7" production ber plugs will be	3800' n water. 9 5/8" an 8 3/4" bit us yill be mudded u or less. Continue casing will be a set as directed	sufficient to ci sufficient to ci sufficient to ci casing will be ing 10 ppg brine p through the re e drilling to PT set at 3800' and d by the NMOCD.	rculate rculate set and cemente , circulating serve pit with D of 3800'. cemented back
8 3/4" 124" hole will so surface. Dri hrough the res starch, MW - 10 f commercial s o surface. If N ABOVE SPACE DESC ONE OIVE BLOWOUT PREVEN hereby certify that the information onature LUM	7" 1 be drilled to 11 out from unde erve pit. At 240 .0 to 10.1, flui hows are present a dry hole, prop RIBE PROPOSED PROGRA THER PROGRAM F AND THER PROGRAM F AND THE PROGRAM F AND TH	400' using fres er surface with a 00', the system w id loss of 6 cc c c, 7" production ber plugs will be	3800' n water. 9 5/8" an 8 3/4" bit us yill be mudded u or less. Continue casing will be s set as directed OR FLUG BACK, GIVE DATA ON P	sufficient to ci sufficient to ci sufficient to ci casing will be ing 10 ppg brine p through the re e drilling to PT set at 3800' and d by the NMOCD.	rculate rculate set and cemente , circulating serve pit with D of 3800'. cemented back
8 3/4" A 12¼" hole will to surface. Dri through the res tarch, MW - 10 f commercial s o surface. If N ABOVE SPACE DESC ONE. GIVE BLOWOUT PREVEN hereby certify that the information on ATURE	1 be drilled to 11 out from unde erve pit. At 240 .0 to 10.1, flui hows are present a dry hole, prop RIBE PROPOSED PROCRA THER PROCRA THER PROPOSED PROCRA THER PROPOSED PROCRA THER PROPOSED PROCRA THER PROPOSED PROCRA THER PROPOSED PROCRA THE PROCRA THE PROCRA THE PROPOSED PROCRA THE PROCRA T	400' using fres er surface with a 00', the system w id loss of 6 cc c c, 7" production ber plugs will be	3800' n water. 9 5/8" an 8 3/4" bit us yill be mudded u or less. Continue casing will be s set as directed OR FLUG BACK, GIVE DATA ON P	sufficient to ci sufficient to ci sufficient to ci casing will be ing 10 ppg brine p through the re e drilling to PT set at 3800' and d by the NMOCD.	rculate rculate set and cemente , circulating serve pit with D of 3800'. cemented back FROPOSED NEW PRODUCTIVE 5/4/92
8 3/4" 124" hole will so surface. Dri hrough the res starch, MW - 10 f commercial s o surface. If N ABOVE SPACE DESC ONE OIVE BLOWOUT PREVEN hereby certify that the information onature LUM	7" 1 be drilled to 11 out from unde erve pit. At 240 .0 to 10.1, flui hows are present a dry hole, prop RIBE PROPOSED PROCRA THER THER PROCRA	400' using fres er surface with a 00', the system w id loss of 6 cc c c, 7" production ber plugs will be	3800' n water. 9 5/8" an 8 3/4" bit us yill be mudded u or less. Continue casing will be s set as directed OR FLUG BACK, GIVE DATA ON P	sufficient to ci sufficient to ci sufficient to ci casing will be ing 10 ppg brine p through the re e drilling to PT set at 3800' and d by the NMOCD.	rculate rculate set and cemente , circulating serve pit with D of 3800'. cemented back

Date Unless Drilling Underway.