Submit 3 Copies to Appropriate District Office	State of New Me Energy, Minerals and Natural Re		J	Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATIO		WELL API NO.	
DISTRICT II Santa Fe, New Mexico 87504-2088		30-025-	31611	
P.O. Drawer DD, Artesia, NM 88210 DISTRICT III			5. Indicate Type of Lease STATE	X FEE
1000 Rio Brazos Rd., Aztec, NM 87410		6. State Oil & Gas Lease No.	A-1375	
SUNDRY N	OTICES AND REPORTS ON WEL	LS	<i>\////////////////////////////////////</i>	
DIFFERENT RE	PROPOSALS TO DRILL OR TO DEEPEN ESERVOIR. USE "APPLICATION FOR PEI IM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreeme	ent Name
1. Type of Well: OIL GAS WELL WELL			State A	
2. Name of Operator			8. Well No.	
	. Arrington Oil & Gas	, Inc.	7	
3. Address of Operator	0071 Midlend Tu	70702	9. Pool name or Wildcat	
4. Well Location	x 2071 Midland, Tx.	/9/02	Eumont-Y-SR-ON	l
;	980 Feet From The North	Line and 1650	) Feet From TheE a S	t Line
Section 2	Township 20 South R	unge 36 East	NMPM	LEA County
	10. Elevation (Show whether		<i>\//////</i>	///////////////////////////////////////
	3588GR, 3598 R		amost or Other Data	
	ck Appropriate Box to Indicate I INTENTION TO:		SEQUENT REPORT	OF:
		REMEDIAL WORK	ALTERING	
		REMEDIAL WORK		
TEMPORARILY ABANDON	CHANGE PLANS			
r				
	CHANGE PLANS	COMMENCE DRILLING		
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed G work) SEE RULE 1103.	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND C OTHER: <u>Drill</u> ad give perfinent dates, inclu	G OPNS. PLUG AND EMENT JOB X Report	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed C work) SEE RULE 1103. 6/9/92 Spudded we J-55 casin Halliburto	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND C OTHER: <u>Drill</u> ad give perfinent dates, inclu ole to 370'. Class C with	GOPNS. PLUGAND EMENTJOB X Report wing estimated date of starting any Ran and cemented 2% CaC/mixed @ 1	ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed C work) SEE RULE 1103. 6/9/92 Spudded we J-55 casin Halliburto OK. 0-14/92 Drilled 7	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND C OTHER: Drill F and give perfinent dates, inclu ole to 370'. Class C with ment to surfa . Ran open ho	GOPNS. PLUGAND EMENTJOB X Report ding estimated date of starting any Ran and cemented 2% CaC/mixed @ 1 ace. Tested casir ole log. Ran and	ABANDONMENT X proposed 1 8 5/8" 24# 4.8#/gal. ag to 1000 ps
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed O work) SEE RULE 1103. 6/9/92 Spudded we J-55 casin Halliburto OK. 10-14/92 Drilled 7 17# J-55 c	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND C OTHER: Drill F ad give perfinent dates, inclu ole to 370'. Class C with ment to surfa . Ran open ho lti-stage cen	GOPNS. PLUG AND EMENT JOB X Report Wing estimated date of starting any Ran and cemented 2% CaC/mixed @ 1 ace. Tested casir ole log. Ran and henter @ 2011'.	ABANDONMENT x proposed 1 8 5/8" 24# 4.8#/gal. ng to 1000 ps cemented 5½"
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed C work) SEE RULE 1103. 6/9/92 Spudded we J-55 casin Halliburto OK. 10-14/92 Drilled 7 17# J-55 c Stage 1: M	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND C OTHER: Drill F ad give perfinent dates, inclu- ole to 370'. Class C with ment to surfa . Ran open ho lti-stage cen on Light Class	GOPNS. PLUG AND EMENT JOB X Report ding estimated date of starting any Ran and cemented 2% CaC/mixed @ 1 Ice. Tested casir ole log. Ran and tenter @ 2011'. S C with 16#/sx	ABANDONMENT x proposed 1 8 5/8" 24# 4.8#/gal. ag to 1000 ps cemented 5½" salt @ 13#/ga
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed C work) SEE RULE 1103. 6/9/92 Spudded we J-55 casin Halliburto OK. 10-14/92 Drilled 7 17# J-55 c Stage 1: M M 3	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND C OTHER: Drill F ad give perfinent dates, inclu- ole to 370'. Class C with ment to surfa . Ran open ho lti-stage cen on Light Class ith 2#/sx Cal d plug, OK. Th	GOPNS. PLUG AND EMENTJOB And Report wing estimated date of starting any Ran and cemented 2% CaC/mixed @ 1 ace. Tested casir ole log. Ran and nenter @ 2011'. S C with 16#/sx Seal,1#/sx KCL, nen opened multi-	ABANDONMENT x proposed 1 8 5/8" 24# 4.8#/gal. ag to 1000 ps cemented 5½" salt @ 13#/ga .0.5% Halad stage cemented
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed C work) SEE RULE 1103. 6/9/92 Spudded we J-55 casin Halliburto 0K. 10-14/92 Drilled 7 17# J-55 c Stage 1: M M 3 0	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND C OTHER: Drill F ad give perfinent dates, inclu- ole to 370'. Class C with ment to surfa . Ran open ho lti-stage cen on Light Class ith 2#/sx Cal d plug,OK. Th out 150/sx co	GOPNS. PLUG AND EMENT JOB And Report ding estimated date of starting any Ran and cemented 2% CaC/mixed @ 1 ace. Tested casir ole log. Ran and nenter @ 2011'. S C with 16#/sx Seal,1#/sx KCL, nen opened multi- cement to surface	ABANDONMENT x proposed 1 8 5/8" 24# 4.8#/gal. ag to 1000 ps cemented 5½" salt @ 13#/ga 0.5% Halad stage cemented
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed C work) SEE RULE 1103. 6/9/92 Spudded we J-55 casin Halliburto OK. 10-14/92 Drilled 7 17# J-55 c Stage 1: M M 3 Q Stage 2: M	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND C OTHER: Drill F ad give perfinent dates, inclu ole to 370'. Class C with ment to surfa . Ran open ho lti-stage cen on Light Class ith 2#/sx Cal d plug,OK. Th out 150/sx co on Light Class	GOPNS. PLUG AND EMENT JOB X Report Wing estimated date of starting any Ran and cemented 2% CaC/mixed @ 1 ace. Tested casir ole log. Ran and henter @ 2011'. S C with 16#/sx Seal,1#/sx KCL, hen opened multi- cement to surface s C with 16#/sx	ABANDONMENT x proposed 1 8 5/8" 24# 4.8#/gal. ag to 1000 ps cemented 5½" salt @ 13#/ga stage cemented stage cemented salt @ 13#/ga
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed C work) SEE RULE 1103. 6/9/92 Spudded we J-55 casin Halliburto OK. 10-14/92 Drilled 7 17# J-55 c Stage 1: M M 3 @ Stage 2: M	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND C OTHER: Drill F ad give perfinent dates, inclu- ole to 370'. Class C with ment to surfa . Ran open ho lti-stage cen on Light Class ith 2#/sx Cal d plug,OK. Th out 150/sx co on Light Class nt to surface	GOPNS. PLUG AND EMENT JOB X Report Ading estimated date of starting any Ran and cemented 2% CaC/mixed @ 1 ace. Tested casir ole log. Ran and nenter @ 2011'. S C with 16#/sx Seal,1#/sx KCL, nen opened multi- cement to surface S C with 16#/sx e. Bumped plug,0k	ABANDONMENT X proposed 1 8 5/8" 24# 4.8#/gal. ag to 1000 ps cemented 5½" salt @ 13#/ga stage cemented salt @ 13#/ga (.WOC 11:30am
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed C work) SEE RULE 1103. 6/9/92 Spudded we J-55 casin Halliburto 0K. 10-14/92 Drilled 7 17# J-55 c Stage 1: M M 3 0 0 Stage 2: M C 1 1 hereby certify that the information above	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND C OTHER: Drill F ad give perfinent dates, inclu- ole to 370'. Class C with ment to surfa . Ran open ho lti-stage cen on Light Class ith 2#/sx Cal d plug,OK. Th out 150/sx co on Light Class nt to surface ng and releas	GOPNS. PLUG AND EMENT JOB T Report ding estimated date of starting any Ran and cemented 2% CaC/mixed @ 1 ace. Tested casir ole log. Ran and tenter @ 2011'. S C with 16#/sx Seal,1#/sx KCL, ten opened multi- cement to surface S C with 16#/sx E. Bumped plug,0k ace rig 2:30pm 6/	ABANDONMENT x proposed 1 8 5/8" 24# 4.8#/gal. ag to 1000 ps cemented 5½" salt @ 13#/ga stage cemented stage cemented salt @ 13#/ga (WOC 11:30am 14/92.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed C work) SEE RULE 1103. 6/9/92 Spudded we J-55 casin Halliburto 0K. 10-14/92 Drilled 7 17# J-55 c Stage 1: M M 3 0 0 Stage 2: M C 1 1 hereby certify that the information above	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND C OTHER: Drill F ad give perfinent dates, inclu- ole to 370'. Class C with ment to surfa . Ran open ho lti-stage cen on Light Class ith 2#/sx Cal d plug,OK. Th out 150/sx co on Light Class nt to surface ng and releas	GOPNS. PLUG AND EMENT JOB T Report ding estimated date of starting any Ran and cemented 2% CaC/mixed @ 1 ace. Tested casir ole log. Ran and tenter @ 2011'. S C with 16#/sx Seal,1#/sx KCL, ten opened multi- cement to surface S C with 16#/sx E. Bumped plug,0k ace rig 2:30pm 6/	ABANDONMENT x proposed 1 8 5/8" 24# 4.8#/gal. ag to 1000 psi cemented 5½" salt @ 13#/ga stage cemented stage cemented salt @ 13#/ga (WOC 11:30am 14/92.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed C work) SEE RULE 1103. 6/9/92 Spudded we J-55 casin Halliburto 0K. 10-14/92 Drilled 7 17# J-55 c Stage 1: M M 3 0 0 Stage 2: M C 1 1 hereby certify that the information above	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND C OTHER: Drill F ad give perfinent dates, inclu- ole to 370'. Class C with ment to surfa . Ran open ho lti-stage cen on Light Class ith 2#/sx Cal d plug,OK. Th out 150/sx co on Light Class nt to surface ng and releas	GOPNS. PLUG AND EMENT JOB X Report ding estimated date of starting any Ran and cemented 2% CaC/mixed @ 1 ace. Tested casir ole log. Ran and tenter @ 2011'. S C with 16#/sx Seal,1#/sx KCL, tem opened multi- cement to surface S C with 16#/sx e. Bumped plug,0k sed rig 2:30pm 6/ DATE 7 (9)	ABANDONMENT X proposed 1 8 5/8" 24# 4.8#/gal. ag to 1000 psi cemented 5½" salt @ 13#/ga stage cemented salt @ 13#/ga (.WOC 11:30am
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed ( work) SEE RULE 1103. 6/9/92 Spudded we J-55 casin Halliburto 0K. 10-14/92 Drilled 7 17# J-55 c Stage 1: M M 3 (P Stage 2: M C 1 hereby certify that the information above SKONATURE David H. TYPE OR FRINT NAME David H.	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND C OTHER: Drill F ad give perfinent dates, inclu- ole to 370'. Class C with ment to surfa . Ran open ho lti-stage cen on Light Class ith 2#/sx Cal d plug,OK. Th out 150/sx co on Light Class nt to surface ng and releas	GOPNS. PLUG AND EMENT JOB X Report ding estimated date of starting any Ran and cemented 2% CaC/mixed @ 1 ace. Tested casir ole log. Ran and tenter @ 2011'. S C with 16#/sx Seal,1#/sx KCL, tem opened multi- cement to surface S C with 16#/sx e. Bumped plug,0k sed rig 2:30pm 6/ DATE 7 (9)	ABANDONMENT x proposed 1 8 5/8" 24# 4.8#/gal. ag to 1000 psi cemented 5½" salt @ 13#/ga stage cemented stage cemented salt @ 13#/ga (WOC 11:30am 14/92. x/15/92 15)