

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 31727
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	TG-314694
7. Lease Name or Unit Agreement Name	VAN ET TEN, L.
8. Well No.	13
9. Pool Name or Wildcat	Weir Blinebry
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3541' GR

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>K</u> : <u>1653</u> Feet From The <u>SOUTH</u> Line and <u>2307</u> Feet From The <u>WEST</u> Line Section <u>9</u> Township <u>20-S</u> Range <u>37-E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3541' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☒ Add additional pay & acidize.

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-11-96; MIRU. INSTALL ONE DEADMAN RU TOH W/ RODS & PUMP INSTALL BOP & TAG BOTTOM @ 6283.
10-12-96: RAN BIT & CASING SCRAPER THRU PERFS 5598'-5614' & to 6283' (PBTD-fill). POH. SHUT IN.
10-14-96: PERF ADDITIONAL WEIR BLINEBRY ZONE W/2 JSPF 5621'-5786' (88'-52" holes). TIH W/ RBP & PKR. TESTED IN TBG AT 7500 psi. SET RBP @ 5802'. SET PKR & TESTED TO 2000 psi-HELD. PULL PKR TO 5573' AND LEFT SWINGING.
10-15-96 SET 5638'. SWABBED FLUID LEVEL. SAND LINE PARTED. TOH LEFT SINKER BAR IN TBG. TIH W/ OVERSHOT ON RODS UNABLE TO FISH. TOH W/ RODS & TOOLS. UNSET PKR & TOH W/ TBG. & PKR LAYDOWN SINKER BAR STUCK IN SN. TH W/ SAME PKR. & LEFT SWINGING ABOVE PERFS. @ 5573'.
10-16-96: D/S ACIDIZE WEIR/BLINEBRY PERFS 5670'-5786'. W/2500 GALS 15% NEFE HCL ACID + 108-7/8", 3ALL SEALERS, MAX TP= 320 PSI, AVG TP= 50 PSI, FINAL TP= 320 PSI, AIR= 4-BPM, ISIP= VAC, SHUT DOWN, RELEASE PKR, RETRIEVE RBP, MOVE & SET RBP @ 5650', TEST RBP, 1000#, OK, RAISE PKR & SET @ 5573', LOAD & TEST CSG TO 500#, OK
10-18-96; SET PKR 5645; RU & PUMP 30 BBLS 2% KCL FRESH DOWN TBG THRU PERFS 5666-5786. MOVE PKR TO 5633 & PUMP 33 BBLS. MOVE PKR TO 5664' PUMP 33 BBLS- TBG ON STRONG VACUUM. LOWER PKR TO 5827' & TEST CIBP TO 700# ok.
10-19-96 RU & RUN PUMP IN TRACER. (PKR SET @ 5645') TIH W/ 1-3/8 GR-DETECTOR & LOG 5500-6276. TCH W/ TOOL RD CARDINAL WL SDFN. NEED TO REACIDIZE W/ ROCKSALT.
10-17-96; RU DOWELL AND ACIDIZE WEIR BLINEBRY PERFS 5598-5629 W/ 2000 GALS 15% NE FE HCL W/ 1/2" 1" BALL SEALERS. PRESSURE BACKSIDE TO 500#OK. MAX PRESS=128#, MIN PRESS=VACUUM, AIR=5.3 BPM. UNSET PKR. & LOWER TO 5650' & LATCH ONTO RBP & POH W/ TBG & TOOLS. TIH W/ 5-1/2 ARROW TENSION PKR. TO 5573' LEFT SWINGING SDFN
10-21-96. LOWER PKR TO 5640' & SET ARROW TENSION PKR. RU DOWELL & RE-ACIDIZE PERFS 5666-5786 W/ 2500 GALS 15% NE FE HCL & 2000# ROCK SALT PUMPED IN 448BLS GELLED BRINE IN 3 STAGES. MAX PRESS=108#, MIN PRESS=VACUUM, AIR=4.1BPM, ISIP=VAC. UNSET PKR & LOWER TO 5700' SET. ACIDIZE PERFS 5724-5786 W/1000 GALS 15% NE FE HCL. MAX PRESS=3300# MIN PRESS=2300#, AIR=1-3/4BPM. ISIP=2300#. SI WELL
10-22-96; UNSET PKR & LAYDOWN WORKSTRING & PKR. TIH W/ 3-1/2X2-7/8 OPSMA, SN, TAC AND TBG. TEG. SET @ 5838', SN SET @ 5821', TAC SET @ 5526'. REMOVE BOP & NU WELLHEAD. TIH W/ GA, PUMP, RODS. HUNG ON, RDMO. SDFN
10-23-96 THRU 11-4-96; PUMPING & TESTING
11-5-96; OPT 101-BO, 53-BW, 200-MCF.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Paula S. Ives TITLE Engineering Assistant DATE 10/23/95

TYPE OR PRINT NAME Paula S. Ives Telephone No. 397-0432

(This space for State Use)

APPROVED BY NOV 21 1995 TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: