

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-31857
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Scharbauer "4"
8. Well No. 1
9. Pool name or Wildcat West Teas (Yates/7 Rivers)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator Mitchell Energy Corporation
3. Address of Operator Box 4000, The Woodlands, TX 77387
4. Well Location Unit Letter <u>O</u> : <u>660</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>4</u> Township <u>20S</u> Range <u>33E</u> NMPM <u>Lea</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3556' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>Recompletion attempt in lower Yates</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1/10/94 POOH w/rods & tbq.
1/11/94 Set CIBP @ 9202' dump bailing 35' cmt on top. Jet cut 5 1/2" csg @ 5401'.
1/12/94 POOH LD 126 jts 5 1/2" csg.
1/13/94 Tag cmt plug @ 9173'. Load hole w/9.5 ppg mud. Spot 25 sx Class "H" neat @ 6608'. Spot 50 sx Class "H" + 3% CaCl₂ @ 5438'. Wait one hour & tag top of cmt plug @ 5323'.
1/14/94 Set CIBP @ 4530'. Perf 3348-64' (9 holes). Acidize w/1000 gals 7 1/2% NeFe.
1/18/94 Swab 21 BW, no shows.
1/19/94 Set CIBP @ 3338'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Greg Colburn TITLE Staff Prod Engineer DATE 2/2/94
TYPE OR PRINT NAME Greg Colburn TELEPHONE NO. (915)682-5396

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

FEB 02 1994

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

OCD HOBBS
OFFICE