たいけい しっしいき Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

1000 Rio Brazos Rd., Aztec, NM 87410

CONDITIONS OF APPROVAL, IF ANY:

OR JONSERVATION DIVISION

P.O. Box 2088

WELL API NO. 30-025-32256	
5. Indicate Type of Lease STATE X FEE	
6. State Oil & Gas Lease No. E-8182	
7. Lease Name or Unit Agreement Name	
West Pearl Queen Unit	
8. Well No. 220	
9. Pool name or Wildcat Pearl Queen	
Feet From The West Line	
NMPM Lea County	
, Report, or Other Data UBSEQUENT REPORT OF:	
ALTERING CASING	
LING OPNS. PLUG AND ABANDONMENT	
CEMENT JOB	
including estimated date of starting any proposed	
nole to 417'. Ran 9 jts. of <u>8 5/8"</u> estern cemented w/190 sks. Class "C" surface. WOC 13 hours.	
ate and condition mud at T.D. Did not casing to 5083'. Cemented casing ass "C" 2% CaCl. Cement did not	W
n and circulate clean to PBTD of 503	38
ots per foot 4752-4766, 4878-4888,	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: X WELL 2. Name of Operator Pyramid Energy, Inc. 3. Address of Operator 10101 Reunion Place, Ste. 210 San Antonio, TX 78216 4. Well Location North 1980 Feet From The Unit Letter $\underline{^{\rm E}}$ Line and 35E 19S 28 Range Township 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3736.7 GR Check Appropriate Box to Indicate Nature of Notice 11. NOTICE OF INTENTION TO: Sl REMEDIAL WORK PLUG AND ABANDON PERFORM REMEDIAL WORK CHANGE PLANS COMMENCE DRILL TEMPORARILY ABANDON CASING TEST AND **PULL OR ALTER CASING** OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, i work) SEE RULE 1103. MIRU Peterson Drlg. Rig #2. Drilled 12 1/4" h 24 # J-55 ST&C casing. Set casing at 414. We 2% CaCl cement. Circulated 21 sks cement to s 10/15/93-11/03/93 Drilled 7 7/8" hole to T.D. of 5087. Circula run open hole logs. Ran 4 1/2" 9.5# J-55 ST&C 865 sxs. PSL with 3# sk. salt and 285 sxs. Cla circulate. 11/10/93 MIRU completion rig. Made bit and scraper run Ran Compensated Neutron CCL Log from 5038-303 Perforated casing with 3 1/8" casing gun 2 sh 11/11/93 4900-4908, 4914-4920, 4942-4950, 4960-4964, 4976-4985, 4995-4999 and 5016-5022. Ran tbg. and packer and acidized perfs. with 3000 gals. 15% HCL. Flow & swab back lo (cont. on back) I hereby certify that the information above is true and complete to the best of my knowledge and belief. THE Operations Mgr. SIGNATURE TELEPHONE NO. TYPE OR PRINT NAME ORIGINAL SIGNED BY JERRY SEXTON (This space for State Use) DISTRICT I SUPERVISOR TITLE APPROVED BY --

- 11/12/93 Circulate out ball sealers and swab back load.
- 11/15/93 Pull packer and tbg. Ran tubing, rods and bottom hold down pump.
- 11/16/93 Set 320-256-100 pumping unit and hooked up electricity. Waiting on flowline.