

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-32465
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Marathon Oil Company		6. State Oil & Gas Lease No.
3. Address of Operator PO Box 2490 Hobbs, NM 88240		7. Lease Name or Unit Agreement Name: W.H. Laughlin
4. Well Location Unit Letter F : 1980 feet from the North line and 2250 feet from the West line Section 9 Township 20-S Range 37-E NMPM County Lea		8. Well No. 6
		9. Pool name or Wildcat Bumont, Yates, 7 Rivers, Queen
10. Elevation (Show whether DR, RKB, RT, GR, etc.) GL 3544', KB 3550'		

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐

OTHER: Add Pay and Stimulate ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

9/25 RU pulling unit. ND wellhead. NU BOP. Tbg parted pulling out of hole. Could not recover. Clean out to 3345'. RIH w/CIBP, set at 3325'. Load & test, OK. POOH.

9/28 RIH w/csg guns. Perf upper Bumont at 3038, 46, 59, 65, 74, 3183, 3218, 55, 72 w/2 SPF, 18 holes. Perf 3101, 04, 23, 31, 3290 w/3SPF, 15 holes. Acidized 3038-3290 w/1300 gals 7.5% Ferchek SC acid. Frac with 32,508 bbls gel w/240 tons CO2 containing 2474 sks of sand. Open to frac tank.

10/12 RIH w/csg guns. Perf 2506, 16, 23, 31, 55, 70, 81, 2621, 58, 2712, 22, 50, 71, 82, 2809, 29, 45, 69, 79, 82 w/1 SPF, 20 holes. Perf 2546, 76, 2651, 2700, 36, 73 w/3 SPF, 18 holes. Acidize 2506-2882 w/3400 gals 7.5% Ferchek SC acid. Frac w/103,440 gals 70Q foam gelled fluid w/238 tons CO2 containing 247,980# sand. Open to frac tank.

10/18 RIH, tag sand at 2919'. Run BHP test.

10/23 RIH w/2 3/8" tbg. Clean out to CIBP at 3325'. ND BOP. NU wellhead. RD pulling unit. F Nipple at 2439' Btm of tbg 2445'

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kelly Cook TITLE Admin. Assistant DATE 10/24/01

Type or print name Kelly Cook Telephone No. 393-7106

(This space for State use)

APPROVED BY _____ TITLE _____ DATE OCT 23 2001

Conditions of approval, if any: