

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO	30 025 32624
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	WILLIAM WEIR
8. Well No.	6
9. Pool Name or Wildcat	MONUMENT ABO

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER HORIZONTAL ☐

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
205 E. Bender, HOBBS, NM 88240

4. Well Location
Unit Letter BHL N : 425 Feet From The SOUTH Line and 1830 Feet From The WEST Line
Section 23 Township 19-S Range 36-E NMPM W140 LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3687'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐ HORIZONTAL COMPLETION ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-25-00: MIRUSU 8-24-00. NUBOP. TIH TO 600'.
8-26-00: TIH W/CSG SCRAPER & BIT TO 7260'. SET RBP @ 7244'. TEST PLUG TO 1000 PSI. DUMP 4' SAND ON TOP. TOP OF SAND @ 7240'.
8-27-00: RDSU.MOVE OUT TBG & RDS.
8-29-00: MIRU KEY #118. INSTL HYD & TEST TO 700 PSI. TIH W/MILL ON DP. TAG RBP @ 7240'.TIH W/WHIPSTOCK SET FACE @ 342.9
AZIMUTH. MILL @ 7228'.
8-30-00: MILL 7228-29,34,37,47,69,78,7422,52,58,72,85,90,7622,30,7717,24,80,7812,25,43,7964,8001,32,8073.TIH W/DP TO 8054'. RUN PUMP DN
TDT LOGS.
9-03-00: TDT LOGS FR 8040-7000. LATCH INTO WHIPSTOCK. JAR LOOSE. TIH W/RBP ON DP. SET RBP @ 7120'.NDBOP. RIG REL @ 0130
HRS 9-03-00.
9-06-00: MIRUSU KEY RIG #319. NDBOP. TIH W/3 1/2" TBG. TIH TO 5800'. RBP @ 7120'.
9-07-00: LATCH RBP @ 7120' & REL. TI W/TBG, PKR & TBG. INSTL FRAC TREE. RAN TBG, SN @ 7119', PKR @ 7126, SUBS.
9-09-00: PUMP 15000 GALS 20% HCL ACID, FLUSH W/3000 GALS 2% KCL. WELL ON VAC.
9-11-00: SET PUMPING UNIT.
9-13-00: ND FRAC TREE & REL PKR.
9-14-00: CIRC WTR DN BACKSIDE TO CIRC OFF SAND. ND PACK-OFF & CIRC EQPT.
9-15-00: TIH W/BAILER TO 7240'. BAIL 7240-7243'. TIH W/TBG TO 7240'.C/O SAND FR 7240-6' BELOW. TAG W/ BAILER. TOH TO 7200' ABOVE
WINDOW.
9-16-00: REL PLUG. TIH W/2 7/8" TBG @ 7187, TA, SN & MA. SN @ 7253'.. TA @ 7197'.SET ANCHOR. NDBOP. INSTL WH.
9-17-00: TIH W/GA, PMP, RDS. RIG DOWN.
9-18-00: START UP WELL @ 0800 HRS ON 9-17-00.
9-26-00: ON 24 HR OPT. PUMPED 23 BO, 294 BW, & 31 MCF. FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 11/21/00

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL IF ANY: TITLE

DATE