

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

NSL-3554(SD)

WELL API NO.	30-025-32722
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	
State E	008657
8. Well No.	6
9. Pool name or Wildcat	076480
Eumont Yates 7R Qn (PG)	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
3637'	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER	2. Name of Operator OXY USA Inc.	16696
3. Address of Operator P.O. Box 50250 Midland, TX 79710	9. Pool name or Wildcat Eumont Yates 7R Qn (PG)	
4. Well Location Unit Letter L : 2145 Feet From The South Line and 495 Feet From The West Line Section 30 Township 19S Range 37E NMPM Lea County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3637'	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Completion ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD - 3750' PBTD - 3705' Perfs - 3360'-3599'

SEE OTHER SIDE

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Stewart TITLE Regulatory Analyst DATE 11/13/95
TYPE OR PRINT NAME David Stewart TELEPHONE NO. 9156855717

(This space for State Use)

NOV 16 1995

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

ATTACHMENT C-103
OXY USA INC.
STATE E #6
SEC 30 T19S R37E
LEA COUNTY, NM

MIRU PU 7/25/95, NU BOP, RIH & TAG @ 3705', TEST CSG TO 2000#, HELD OK, CIRC W/ 2% KCL WATER. RIH W/ CBL-GR-CCL FROM 3700-1000'. PERF QUEEN W/ 1SPF @ 3360-62, 67-69, 94-3397, 3406-25, 32-50, 52-62, 74-76, 86-89, 96-3498, 3513-15, 19-27, 31-36, 46-48, 53-61, 73-82, 95-3599' TOTAL 115 HOLES. RIH W/ BAKER LOC-SET PKR, ON/OFF TOOL, W/ 1.87 PROF NIP & SET PKR @ 3255'. ACIDIZE W/ 5000 GAL 7-1/2% NEFE HCL ACID, MAXP-2200#, ISIP-1200#. SWAB & FLOWBACK 0-BO, 19-BW IN 7 HRS, FLOW ALL GAS LAST 2 HRS. 42HR SITP-200#, FRAC W/ 36808 GAL 50 QUALITY GELLED 2% KCL & CO2 W/ 67000# 12/20 SAND, MAXP-6400#, ISIP-2180#, OPEN WELL TO PIT FOR 3HRS FOR 43-BLW. RIH W/ SINKER BAR & TAG SAND @ 3000'. SITP-180#, FLOW BACK CO2, FTP-170# IN 2HRS. RU COIL TBG, WASH SAND FROM 3000' TO 3700', JET HOLE CLEAN. OPEN WELL TO PIT & SWAB 0-BO, 1-BW IN 3HRS. RIH W/ BLK PLG, POOH W/ WS TBG & RIH W/ 2-3/8" TBG & LATCH ONTO ON/OFF TOOL, NDBOP, NUWH, TEST TO 1500#, HELD OK. SITP-165#, OPEN WELL TO PIT & SWAB BACK 0-BO, 6-BLW. SITP-160#, FLOW WELL TO PIT FOR 4HRS ON 14/84 CHK W/ 32#-FTP, NO FLUID, SWAB 1 BLW IN 6 HRS. RDPU 8/10/95, SI TO BUILD PRESS. 8/10-8/29/95.

SITP-160#, RUPU 8/30/95, RIH & SET BLK PLG, LOAD TBG, TEST TO 1000#, HELD OK, NDWH, NU BOP, SWAB 0-BO & 69-BW IN 5 HRS. POOH W/ PKR, ON/OFF TOOL & TBG. RIH W/ 2-3/8 TBG & SET @ 3682, ND BOP, NUWH. RIH W/ 2"X 1-1/2"X 12' BHD PUMP ON 66 RD STR, RDPU 8/31/95. SI WO PARTS TO REPAIR ENGINE 9/1/-9/7/95. TRY TO PUMP & FLOW TEST WELL FROM 9/8-9/11/95 FOR 0-FLUID & 826 MCF. SI WO PL CONN.

CONNECT WELL TO GPM & RUN 1PT 24 HR FLOW TEST 9/29/95 W/ A RATE OF 388MCFD @ 38#-FTP.

Received
Hobbs
000