

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-32742
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	000194
7. Lease Name or Unit Agreement Name	STATE "J" GAS COM.
8. Well No.	7
9. Pool name or Wildcat	EUMONT YATES 7RQ

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT' (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER	
2. Name of Operator AMERADA HESS CORPORATION	
3. Address of Operator P.O. BOX 2040 HOUSTON, TEXAS 77252	
4. Well Location Unit Letter <u>M</u> : <u>2422</u> Feet From The <u>NORTH</u> Line and <u>990</u> Feet From The <u>WEST</u> Line Section <u>2</u> Township <u>20S</u> Range <u>36E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3598 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☒
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☒
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 12-01-94 M.I. & R.U. MCGEE RIG #1. SPUD WELL @ 3:00 P.M. MST. 40' STARTING HOLE + 15' KB = 55'. DRILL F/55'-418'. CIRC. TO RUN 8-5/8" CSG. RUN 10 JTS 8-5/8" 24# M 80 HC 8RS SM'S R3 "A" CSG. SHOE @ 417.50' INSERT FLOAT @ 375.38'. CMT. W/HALLIBURTON - PUMP 250 SX CLASS "C" + 2% CAL/2 (14.8# - 1.32). DISPL. W/24 BBLS. F. WATER @ 5 BBLS/MIN. FINAL CIRC. W/300 PSI. BUMP PLUG W/650 PSI @ 10:00 P.M. MST. FLOAT HELD O.K. CIRC. 60 SX CMT TO PIT. WOC 18 HRS. TEST CSG. W/800 PSI. DRILL TO 3,600'. CIRC. & RUN 84 JTS 5-1/2" 15.50# K-55 8RS SM'S R3 "A" CSG. CMT W/HOWCO - PUMP 250 SX CLASS "C" + HELLI-LITE + 5#/SX SALT + 1/4# SX C.F. (12.6# - 2.00). 250 SX CLASS "H" + 5#/SX CEL-SPAL (16# 1.17). BUMP PLUG W/1200 PSI @ 7:00 P.M. 12-07-94 MST. OPEN STAGE TOOL W/850 PSI. CIRC. 70 SX CMT TO PIT. CMT 2ND STAGE. PUMP 375 SX CLASS "C" + HELLI-LITE + 5#/SX SALT + 1/4# /SX C.F. (12.6# - 2.00). 300 SX CLASS "H" + 5#/SX. (16# - 1.17). FINAL CIRC. W/700 PSI. BUMP PLUG & CLOSE STAGE TOOL W/2100 PSI @ 12:00 A.M. 12-08-94 MST. CIRC. 64 SX CMT TO PIT. RELEASE RIG @ 4:00 A.M. 12-08-94

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mike Jumper TITLE SUPVSR. DRLG. SVS. DATE 12-12-94
TYPE OR PRINT NAME MIKE JUMPER (713)
TELEPHONE NO. 609-4846

(This space for State Use)
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

DEC 16 1994