

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-33006
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	W.A. WEIR GAS COM
8. Well No.	9
9. Pool name or Wildcat	EUMONT YATES 7 RQ

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator Amerada Hess Corporation	
3. Address of Operator P. O. Box 840, Seminole, Texas 79360-0840	
4. Well Location Unit Letter <u>D</u> : <u>330</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>WEST</u> Line Section <u>2</u> Township <u>20S</u> Range <u>36E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3608' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-29-1997 THRU

MIRU DAWSON WELL SVC. BLOW DWN PRESSURE & PUMP 35 BBS. WTR DWN CASING. INSTALL BOP. TOH W/2-7/8" TBG, 2-7/8" SN. TIH W/ BAKER LOC-SET BP, 5-1/2" X 2-7/8" ON/OFF TOOL, BAKER MODEL 'R' PKR, COLLAR LOCATOR, 2-7/8" TBG TO 3410'. FOUND COLLARS & SET BP @3416'. RELEASE ON/OFF TOOL. CIRC. W/2% KCL W/LO-SURF 300 WTR. CI. OPEN WELL & CIRC. HOLE W/2% KCL WTR. SET PKR @3400' & PRESS. TBG & BP TO 3500# PRESS. FOR 15 MIN. OK. RELEASED PKR & PRESS. CASING TO 3500#; OK. RD KILL TRUCK. TOH W/2-7/8" TBG, BAKER PKR. TIH W/2-7/8" TBG OPEN ENDED. MIRU FRAC MASTERS. PUMP 600 GAS. 15% HCL TO 3360'. REVERSE OUT TO FRAC TANK. SOPT 400 GAS. 15% HCL NEFE W/70# PER 1000 GALS. SODIUM ERYTHORBATE FROM 3360 - 2960. FLUSH W/2%KCL WTR W/LO-SURF 300 & 3 SACKS 20-40 SAND. RD FRAC MASTERS.
CON'T PAGE 2

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Colleen Robinson TITLE STAFF ASSISTANT DATE 11/17/1997

TYPE OR PRINT NAME COLLEEN ROBINSON TELEPHONE NO. 915 758-6778

(This space for State Use)

ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

DEC 11 1997