

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 33296
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	15340
7. Lease Name or Unit Agreement Name	ANDERSON, T.
8. Well No.	5
9. Pool Name or Wildcat	MONUMENT PADDOCK
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3543' GL

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>I</u> : <u>1650'</u> Feet From The <u>SOUTH</u> Line and <u>430'</u> Feet From The <u>EAST</u> Line Section <u>8</u> Township <u>20S</u> Range <u>37E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3543' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☒ ACIDIZE, PERF PADDOCK

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-19-99: MIRU. SHOT FL @ 4869'. TOH W/SUBS, RODS, & PMP. NDWH. NUBOP. REL TAC. TIH W/BIT, CSG SCRAPER, & 2 7/8" TBG TO 5734'. HOT OIL TBG W/50 BBLS 2% KCL W/PARAFFIN DISP. TOH W/TBG.
1-20-99: TIH W/CIBP & SET @ 5510'. TIH W/PERF GUN. PERF PADDOCK CSG PERFS FR 5142-5230'. TIH W/PKR, SN, & TBG TESTED TO 5000#. LERT PKR SWINGING @ 5255'. CIRC HLE W/130 BBLS 2% KCL. PULL PKR TO 5135'.
1-21-99: PULL PKR TO 5015' & SET. SPOT ACID TO PKR. PRESS BACKSIDE TO 600#-OK. ACIDIZE PADDOCK PERFS 5142-5230' W/1800 GALS 15% NEFE HCL. RU SWAB. FL @ 2000'. END FL @ 2400'.
1-22-99: START FL @ 2000'. SWAB. REL PKR & TIH W/10 JTS 2 7/8" TBG TO 5511'. KNOCK OFF BALLS. TOH W/TBG & PKR.
1-23-99: TIH W/CMT RET, SN, & TBG TO 5040'. PUMP THRU RET W/30 BFW. SET RET @ 5040'. PRESS CSG TO 500#-OK. SQUEEZE PADDOCK PERFS 5142-5230' W/200 SX CL C W/2% DO46 ANTI FOAMER. UNABLE TO OBTAIN SQUEEZE. TBG ON VAC. CLEAR RET & OVERFLUSH W/10 BBLS. MIX & PUMP 175 SX CL C W/SAME ADDITIVES. END PRESS-1700# @ 1 BPM. FLSH W/25 BBLS. STING OUT OF RET. REV OUT. → OK
1-24-99: RU REV UNIT. TIH W/NEW BIT, DC'S & TBG. TAG CMT RET @ 5036'.
1-26-99: LOWER TOOLS & BREAK CIRC. DRILL UP CMT RET @ 5040'. DRILL MEDIUM HARD CMT FR 5040-6258' CIRC CLN. TEST & CHART TO 320# FOR 30 MIN-OK. PULL TO 5150'.
1-27-99: CIRC HLE W/CLEAN 2% KCL. LOWER TOOLS & TAG CIBP @ 5510'. DRILL UP CIBP IN 4 HRS. PUSH TO 5825'. PBD @ 5833'-OK. LOST CIRC. TOH W/TBG. LD COLLARS & BIT.
1-28-99: RU PUMP TRUCK. KILL WELL W/30 BBLS 2% KCL WATER. TIH W/PKR, SN, & TBG. PSA 5500'. LOAD & TEST BACKSIDE TO 300#-OK. ACIDIZE BLUEBERRY PERFS FR 5580-5717' W/2082 GALS 15% NEFE HCL W/MUTUAL SOLVENT & 2000# RK SLT. FL @ 4500'. SWAB. END FL @ 5100'. REL PKR. TIH W/TBG. TAG SALT FILL @ 5722'. RU PUMP TRUCK & C/O SALT FILL TO 5783'.
1-29-99: KILL WELL. TIH W/OPSMA, SN, TBG, TAC. KB @ 13'. BTM OF MA @ 5767'. SN @ 5734'. TAC @ 5556'. NDBOP. NUWH. TIH W/GAS ANCHOR, PUMP, & RDS. LOAD & TEST TO 500#-OK. HUNG ON. RIG DOWN. PUMPING 7X120"SPM. LEFT WELL DOWN. WELL PRESSURED UP TO 400# ON FLOWLINE.
3-09-99: ON 24 HR OPT. PUMPING 14 BO, 6 BW, & 28 MCF.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 3/15/99

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 620-2001-0405

(This space for State Use)

APPROVED BY _____ TITLE _____

DATE JAN 16 2000

CONDITIONS OF APPROVAL, IF ANY:

