

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30 025 33306

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil / Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
205 E. Bender, HOBBS, NM 88240

4. Well Location
Unit Letter E : 1700 Feet From The NORTH Line and 940 Feet From The WEST Line
Section 6 Township 20S Range 37E NMPI LEA COUNTY

7. Lease Name or Unit Agreement Name

PHILLIPS, J. R.

8. Well No.

13

9. Pool Name or Wildcat

EUMONT 7R QUEEN

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3567' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒

ALTERING CASING ☐

COMMENCE DRILLING OPERATION ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

Recomplete in Eumont

☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-26-99: MIRU. NDWH. NUBOP.

7-27-99: TIH W/PERF GUN & PERF IN UPPER QUEEN FORMATION 3038-40,3068-76,3122-34. TIH & PERF 3150-52,3156-58,3162-64. TIH W/PKR, SN, ON TBG. SET PKR @ 2912'. TEST BACKSIDE TO 500#-OK.

7-28-99: ACIDIZE UPPER QUEEN PERFS FR 3038-3164' W/2500 GALS 15% NEFE HCL & 500# RK SLT. SWAB. REL PKR. TIH W/OPSMA, SN, TBG, TAC. MA @ 3226'. SN @ 3194'. TAC @ 2973'. NDBOP. NUWY. RU SWAB. FL @ 2700'. END FL @ 2700'.

7-29-99: RU SWAB. TIH TO SN @ 3194'.

7-30-99: TIH W/SWAB. TAG FLUID @ 3100'. SN @ 3194'.

8-02-99: NDWH. NUBOP. REL TAC. TIH W/SN, & TBG TO 3753'. FL @ 3100'. END FL @ 3600'.

8-03-99: SWAB DRY. RD SWAB. TIH W/CIBP & SET @ 2988'. TIH W/BAILER. DUMP 35' CMT ON TOP OF CIBP. TIH W/2 3/8" TBG OPEN ENDED TO 1500'. LOWER TBG TO 2935'. RU KILL TRUCK & CIRC W/90 BBLs PKR FLUID. TEST & CHART FOR NMOCD TO 500#-30 MINS. NDBOP. NU FLANGE W/BALL VALVE. RIG DOWN. WELL IS TA'D.

FINAL REPORT

This Approval of Temporary
Abandonment Expires

9/24/2004

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 09/01/1999

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

ORIGINAL SIGNATURE OF CHRIS WILLIAMS
DISTRICT SUPERVISOR

APPROVED BY _____ TITLE _____

DATE

SEP 24 1999

CONDITIONS OF APPROVAL, IF ANY:

JC 61

dp