

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 33359
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	PHILLIPS, J.R.
8. Well No.	14
9. Pool Name or Wildcat	EUMONT YATES SEVEN RIVERS QUEEN (PRO GAS)

SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well:	OIL WELL ☐ GAS WELL ☒ OTHER
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>D</u> : <u>760</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>WEST</u> Line Section <u>6</u> Township <u>20S</u> Range <u>37E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3585 GL

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
 PULL OR ALTER CASING ☐
 OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
 COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
 CASING TEST AND CEMENT JOB ☐
 OTHER: ☐ Add Pay & Acidie ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-21-99: MIRU. KILL WELL W/30 BBLS 2% KCL. NDWH. NUBOP. PU 5 JTS & TAG TD. TIH W/BIT, & CSG SCRAPER. PU WS. RAN BIT TO 3290'. (PBSD @ 3446'). BTM PERF @ 3260'. PULL BIT TO 1500'.
 6-22-99: TIH W/PKR, SN. SET PKR @ 3137'. LOAD & TEST BACKSIDE TO 500#-OK. ACIDIZE YATES 7R: QUEEN PERFS 3198-3260' W/3000 GALS 15% NEFE HCL & 2000# RK SLT. RU SWAB. FL @ 2600'.
 6-23-99: TIH W/PERF GUN & PERF 3046-48, 3074-86, 3128-34, 3138-40, 3142-44. TIH W/RBP & PKR ON 2 3/8" TBG. SET RBP @ 3177'. SET PKR @ 3175'. TEST RBP TO 1000#-OK. REL & PULL UP TO 3142'. SPOT 3 BBLS 15% NEFE HCL ACR PERFS. PULL PKR TO 2850'. SET PKR @ 2950'. ACIDIZE YATES PERFS 3046-3144' W/2400 GALS 15% NEFE HCL. RU SWAB. FL @ 2550'. END FL @ 2900'.
 6-24-99: FL @ 2850'. REL PKR & LOWER TO 3177'. LATCH & REL RBP. TIH W/OLD PROD TBG. TIH W/OPSPMA, SN, TBG. KB-12.8'. MA @ 3267'. SN @ 3234'. TAC @ 2944'. NDBOP. NUWH.
 6-25-99: TIH W/GAS ANCHOR, PUMP, RDS, SNKR BARS. NUWH. LOAD & TEST TBG TO 500#-OK. HUNG ON. RIG DOWN. PUMPING @ 2:00 PM.
 6-27-99: ON 24 HR OPT. PUMPED 0 BO, 10 BW, & 440 MCF.
 FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 09/01/1999
 TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use) ORIGINAL SIGNED BY

APPROVED BY GARY WINK TITLE FIELD REP. II DATE 9-10-99
 CONDITIONS OF APPROVAL, IF ANY: