N. M. OIL CON' OMMISSION P. O. BOX 1980 HOBBS, NEW MEXICO 882

Form 3160-5

UNITED STATES

FORM APPROVED

MEXICO	8824n	Budget Eureau No. 1004-0135
		Expires: March 31, 1993
	5. L	case Designation and Serial No.

	ELAND MANAGEMENT	Expires: March 31, 1993		
	F LAND MANAGEMENT	5. Lease Designation and Serial No.		
SUNDRY NOTICES	NM - 87274 6. If Indian, Allottee or Tribe Name			
Do not use this form for proposals to d	5. It mutan, Another of Tibe Name			
USE APPLICATION FO	OR PERMIT - * for such proposals			
SUBM	7. If Unit or CA, Agreement Designation			
1. Type of Weil		-		
Oil X Gas Well Other	8. Well Name and No.			
2. Name of Operator Santa Fo Engrav Possurges	Topaz "30" Fed Com #1			
Santa Fe Energy Resources, 3. Address and Telephone No.	9. API Well No.			
550 W. Texas, Suite 1330, Mic	30-025-33:375			
4. Location of Well (Footage, Sec., T., R., M., or Survey	10. Field and Pool, or exploratory Area			
(E), 1980' FNL & 660' FWL,	West Lynch (Morrow)			
	11. County or Perish, State			
CHECK APPROPRIATE POW	Lea NM			
	(s) TO INDICATE NATURE OF NOTICE, REPORT,	OR OTHER DATA		
TYPE OF SUBMISSION				
Notice of Intent	Abandonment	Change of Plans		
[▼]	Recompletion	New Construction		
Subsequent Report	Plugging Back	Non-Routi to Fracturing		
Final Abandonment Notice	Casing Repair	Water Shul-Off		
	Altering Casing	Conversion to Injection		
	X other Ran casing string	Dispose Water (Note: Report results of multiple completion on Well		
. Describe Proposed or Completed Operations (Clearly state	all pertinent details, and give pertinent dates, including estimated date of startin	Completion of Personal star Demand and London		
	sopals for an markets and zones perdirent to this work.	s any proposed work. It went is directionally drie		
3/20/96: TD 17-1/2" hole @ 317	2'. RU casing crew.			
1/21/96: Pan total of 70 its 1	2 2/9" 60# 6 00			
1/21/96: Ran total of 78 jts 13-3/8" 68# S-80 casing and set at 3172'. Cemented w/ 2500 sx 3-Lite followed w/ 250 sx Cl "C" + 2% CaCl2. Plug down at 3:00 a.m. Circ'd 485 sx to pit.				
OC. Cut csg off and weld on h	lead. Tested weld. ok.	Circ d 485 SX to pit.		
/22/96: Testing wellhead. NU si, ok. Check drill collars (BOP and choke manifold. Test casing a	and blind rams to 600		
or, or. check diffi collars (had bad pin on XO sub). Waiting on new	v XO sub.		
/23/96: PU DC's and TIH w/ BH	A. Test hydril and pipe rams to 600 ps	si ok —Drilling plug		
nd shoe joint.	, and pripe 1 ame to 500 pc			
HOBBS				
ACCE	да он 80 он 90 он			
DATE	ECEIV 26 52 F AU OF LAND HOBBS, NM			
SIGNATUF	EIV 1 52 F			
		I = 1		
4. I hereby cerully that the foregoing is true and correct	Tonne McCollege	¥ 3 D		
	ou gritte Terry McCullough	Date 4/24796		
(This space for Federal or State office use)				
Approved by	Title	Date		
•				