Submit 3 copies

State of New Mexico

Form C-103

to Appropriate E y, Minerals and Natural Resources De District Office	partment Revised 1-1-89
OIL CONSERVATION DIV	
P.O. Box 1980, Hobbs, NM 88240	30 025 33391
P.O. Box Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2	
DISTRICT III	STATE STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil / Gas Lease No. NM55758
SUNDRY NOTICES AND REPORTS ON WELL	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT	7. Lease Maine of Onk Agreement Maine
(FORM C-101) FOR SUCH PROPOSALS.)	AMERICAN NATIONAL KEOHANE CAS COM
1. Type of Well: OIL GAS WELL OTHER	
2. Name of Operator	8. Well No.
TEXACO EXPLORATION & PRODUCTION INC.	
3. Address of Operator 205 E. Bender, HOBBS, NM 88240	9. Pool Name or Wildcat EUMONT YATES 7 RVRS QN (PRO GAS)
4. Well Location	
Unit Letter <u>E : 1980</u> Feet From The <u>NORTH</u> Line and <u>990</u> Feet From The <u>WEST</u> Line	
Section 18 Township 19-S Range 37-E NMPM LEA COUNTY	
10. Elevation (Show whether DF, RKB, RT,GR, etc.) 3705'	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPERATION PLUG AND ABANDONMENT	
	ST AND CEMENT JOB
OTHER:	PERF & ACIDIZED
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. PULLED TO 3000'. 	
8-29-96 RUWL, TIH W/4" GUN. PERF QUEEN W/3JSPF FROM 3572 TO 3664'. TOTAL OF 92'. RDWL, TIH W/PKR, TEST T/5000#, LEFT PKR. SWINGING @ 3502' SIFN.	
8-30-96 ACIDIZE PERFS. SWAB 3 RUNS, SWABBED WELL DRY, REEC 7 BLW, TOH, SDFN.	
8-31-96 TIH W/5-1/2" ARROW PKR ON 111 JTS 3-1/2 9.3# WS TESTED TO 8000#. SET PKR @3486'. NU FRAC TREE & TESTED. OK SDFN. 9-01-96 DOWELL FRAC EUMONT PERFS 3572'-3664' W/69,000 GALS. SANDED OUT W/10248# RESIN COATED SAND IN TBG. PRESS. BLEED	
OFF. SI.	
9-04-96 RIG UP DOWELL COIL TUBING UNIT. TAG SAND @1686' INSIDE 3.5" FRAC TUBING. POH 9-05-96 FINISH LAYING DOWN TUBING. SDFN	
9-06-96 TIH W/ 4-3/4 BIT ON 2-3/8 TBG. TAG SAND IN CSG. @3581' CLEAN OUT TO PBTD. (3672') W/ FOAM UNIT. TOH TIH W/2-3/8 W/ 4' PERF. SUB., SN, AND 121 JTS 2-3/8 4.7#, 8R, EUE WC-50 TBG. SET @ 3647', SN SET @ 3614' REMOVED BOP &NU WELLHEAD SDFN. 9-07-96 TIH W/ 1"X10' GAS ANCHOR, 2"X1-1/4X16' PUMP ON 143-3/4"X25' RODS. RDMO PRIDE. HOOK UP WELLHEAD. SIFN. 9-08-96 STARTED UP 7:30 AM TESTING THUR ROLO.	
9-09-96 RECOVERED 0-BO, 2-BW, 34-MCF. 9-14-96 HOOK UP TO TRMI SALES METER.	
10-7-96 OPT PUMPING, 0 BOPD, 5 BWPD, 86 MCFPD.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE AUCKURAL TITLE Field Technician	DATE 11/18/96