

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-33436
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. N/A
7. Lease Name or Unit Agreement Name SMITH
8. Well No. 8
9. Pool name or Wildcat MONUMENT/ABO

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator AMERADA HESS CORPORATION
3. Address of Operator P.O. BOX 2040 HOUSTON, TEXAS 77252	4. Well Location Unit Letter <u>H</u> : 1980 Feet From The <u>NORTH</u> Line and <u>860</u> Feet From The <u>EAST</u> Line Section <u>34</u> Township <u>19S</u> Range <u>36E</u> NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3638' GR.	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>
	OTHER: SPUD & RUNNING SURF. CSG. <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

05-22-96: MOVE IN AND RIG UP MCGEE RIG #1.

05-23-96: SPUD WELL AT 6:00 A.M. (40' OF 14" COND. + 17' KB = 57'). DRILL FROM 57' TO 466'. (SURVEY 1/4°). DRILL FROM 466' TO 879'. (SURVEY 3/4°) T.I.H. W/BIT #2.

05-24-96: DRILL FROM 879' TO 1,260' (SURVEY 1/4°) R.U. BULL ROGERS CSG. CREW AND RUN 31 JTS. 8-5/8", 24#, K-55, 8RS, SMLS, R3, A, CSG. SET AT 1,260', SHOE AT 1,259', F.C. AT 1,217', RAN 10 CENT. CMT. WITH DOWELL. PUMP 30 BBLS. OF FRESH WATER. CMT. WITH 250 SX. CL. C + 4% GEL + 2% CACL2 + 1/4#/SX C.F. (13.7# 1.67) TAIL WITH 200 SX. CL. C, + 2% CACL2, + 1/4 #/SX. C.F. (14.8# 1.32) BUMP PLUG WITH 1250 PSI AT 4:30 P.M. FLOAT HELD O.K. CIRC. 34 SX. CMT. TO PIT.

05-25-96: TEST CSG. WITH 1000 PSI FOR 30 MIN. TEST O.K.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mike Jumper TITLE ADM. SUPERVISOR DRILLING SVS DATE 05-28-96
TYPE OR PRINT NAME MIKE JUMPER TELEPHONE NO. (713) 609-4846

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JUN 16 1996

